# Company Company

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF NICHIGAN
MIDLAND COUNTY
REHOMINENTATION & FILEI

HIDLAND COUR	([	1	
REHONUMENTATION	ů.	FIL	E

& File Number

	dland (County)	Located In:	REMONUMENTATION Corner Code ##	HIDLAND COUNTY REMONUMENTATION & FIL
1.	Public Land Survey	Т <sup>14N</sup> R 2	2W B-5	30 NOV 93 3:10 P.H.
		T R _ T R _ T R _		BEVERLY J THAYER REGISTER OF DEEDS
2.	Property Controlling in Section	S T R _ S T R _	1	
3.	Miscellaneous Property in Sec.	S T R _ S T R _		Register of Deeds Stamp & File No
				2 - 6 - 5 - 4 - 3
				3

, in a field survey on May . 19 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

10 11 12 13

A. Description of original monument and accessories and/or subsequent restoration:

### (8-5) 1/4 Cor, Sec. 7 & 18, T14N-R2W

Wood Post Placed by Joel Whight in 1832 Sub. of Twp.: N67°W 19 L. (3.822M) 10"(25.5cm) Maple; S49°E 27 L. (5.432M) 10" (25.5cm) Hemlock.

L.C.R.C. by P. Lapham, Recorded in Bk. 1 P. 528, Set 13mm capped Rerod by Single Proportionate Meas.: N45°W 4.02M 20cm Cedar; North 1.16M 20cm Birch; S45°W1.86M 10cm Pipeline Marker; South 24.44M CL M-20.

L.C.R.C. by H. Fluharty, Recorded in Bk. 1 P. 585, Found 13mm iron w/cap 24.44M N, of CL M-20: N68°E 1.640M 10cm Cedar; N15°E 1.189M 20cm Birch; N40°W 4.081M 30CM Cedar. (Survey in L. 3, P. 565)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

## (B-5) 1/4 Cor. Sec. 7 & 18, T14N-R2W

Found 13mm Iron Rod w/cap #9433 per Bk. 1 Pgs. 528 and 585.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: WHAT OF BICH

#### 1/4 Cor., Sec. 7 & 18, T14N-R2W <u>(B-5)</u>

Signed by \_

Surveyor's Michigan License No. \_

Found 13mm Iron Rod w/cap #9433 per Bk. 1 Pgs. 528 & 585, and is accepted as a careful and faithful reestablishment of the position of the original corner.

N40°W 4.074M 25cm Cedar(R) ND2°E 1.190M 15cm White Birch(R) N64°E 1.634M 15cm Cedar(R) SB0°E 17.688M MDOT R/W Marker (Nail on Top) South 24.445M CL M-20

POFESSION WHITE SELLING NOV

STATE OF MICHIGAL

NORMAN C.

CALDWELL CFESSIONAL

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975