

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Midland
(County)

Located In

Corner Code #

1. Public Land Survey T _____ R _____
T _____ R _____
2. Property Controlling in Section S 31 T 15N R 1W 2
S 31 T 15N R 1W 6
3. Miscellaneous Property in Section S _____ T _____ R _____
S _____ T _____ R _____

4. Lot No: _____ Recorded Plat: _____

5. Private Claims: _____

I, Craig W. McVean, in a field survey on April 18, 2012 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5			4			3		2	1
3													
4	7		8			9			10		11		12
5													
6	18		17			16			15		14		13
7													
8	19		20			21			22		23		24
9													
10	30		29			28			27		26		25
11													
12	31		32			33			34		35		36
13													

A. Description of original monument and accessories and/or subsequent restoration:

2 - None

6 - None



B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

2 - E 1/16 Corner common to Sec. 30 & 31 - Set 2" Alum. Cap on 5/8" x 34" iron rebar is per Standard BLM procedure.

6 - NE 1/16 Cor. Sec. 31 - Set 2" Alum. Cap on 5/8" x 4" long iron rebar at intersection of 1/16 Lines between found 1/16 corners at comers #5, 7, & 9 and set corner #2. Corner in Hardwood swamp. Intermittent stream S. is 18'± West.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

2 - Stamped 2" Alum. Cap on 5/8" x 34" iron rebar
N80°W 30.48' to set N & T in S. side 5" R. Maple
N16°W 27.04' to set N & T in W. side 11" Oak
S72°E 8.12' to set N & T in S. side 9" Oak
S2°E 28.97' to set N & T in W. side 9" Oak
Set Blue Carsonite Post with Loc. tag 1' NE

6 - Stamped 2" Alum. Cap on 5/8" x 4" long iron rebar.
Set Blue Carsonite Post with Loc. tag 1' NE
N35°E 22.32' to set N & T in SE side Tw. 7" and 12" Ash
N56°E 33.73' to set N & T in NW side 5" Elm
S12°W 5.16' to set N & T in E. side 11" Ash
N85°W 37.56' to set N & T in N. side 16" W. Oak

Signed by:

Craig W. McVean

Date:

12/10/2012

Surveyor's Michigan License No.:

39088