

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in  
**MIDLAND**

(County)

Located In:

Corner Code ~~##~~

- |                         |   |            |   |           |                   |
|-------------------------|---|------------|---|-----------|-------------------|
| 1. Public Land Survey   | T | <u>15N</u> | R | <u>2W</u> | <u>F-10, F-11</u> |
|                         | T |            | R |           |                   |
|                         | T |            | R |           |                   |
|                         | T |            | R |           |                   |
| 2. Property Controlling | S | <u>28</u>  | T | R         | <u>B, 15</u>      |
| in Section              | S |            | T | R         |                   |
| 3. Miscellaneous        | S |            | T | R         |                   |
| Property in Sec.        | S |            | T | R         |                   |

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_
5. Private Claims \_\_\_\_\_

I, C. F. ROSER, in a field survey on 11-30, 19 90,  
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned  
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the  
current manual of survey instructions of the United States Department of the Interior, Bureau of Land  
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5  
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a  
Court of Law; established, re-established, monumented, re-monumented, recovered, found as  
expressed below:

**NOTE:** Not more than 4 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

F-10

F-11

8

15

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

F-10

F-11

8

15

FD & ACCETED "T" IRON AS ESTAB  
BY RUDELL ENG INC FOR CTR OF  
SEC 28. E-W TRAIL RD IS 49'  
SOUTH AND TRAIL RD TO SOUTH IS  
170' EAST.

REESTAB. S1/4 COR SEC 28 ON  
LINE AND DOUBLE DISTANCE  
ACROSS FD N1/4 COR AND FD CTR  
OF SEC. 28 (N1/4 COR & CTR  
ESTAB. BY RUDELL ENG INC IN  
1982 SURVEY). N-S TRAIL IS  
315'± E.

ESTABLISHED NE COR OF N1/2 OF  
SW1/4 OF SEC 28 PER STANDARD  
BLM INSTRUCTIONS. COR FALLS AT  
EAST EDGE OF CLEAR CUT AREA.  
E-W TRAIL RD IS 30' SOUTH,  
TRAIL RD TO SOUTH IS 182'  
WEST.

ESTABLISHED SE COR OF N1/2 OF  
SW1/4 SEC 28 PER STANDARD BLM  
INSTRUCTIONS. CORNER FALLS  
NEAR SD. EDGE OF 140'±  
DIAMETER WET SWAMP HOLE. E-W  
TRAIL RD IS 10' SOUTH AND  
TRAIL RD TO NORTH IS 92'±  
WEST.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F-10

F-11

8

15

FD. T IRON, ADDED 1"x 4" GALV.  
PIPE W/RLS CAP & STL FN POST.  
10" ASH N34°W 22.6'  
18" R.PINE N75°E 100.7'  
27" SWP.OAK S15°E 39.8'  
12" ASH S35°W 56.8'  
7" TWIN ASH S75°W 11.5'

DROVE 1"x 4" GALV PIPE W/ALUM.  
DNR CAP & SET CEDAR POST.  
10" G.ASH N25°E 11.1'  
4" MAPLE S45°E 22.7'  
14" G.ASH S60°W 27.9'  
5" ELM S75°W 30.0'

DROVE 5/8"x 3/4" REROD W/RLS  
CAP & SET CED POST W/LOC TAG.  
12" MAPLE NORTH 63.4'  
4" R.OAK N60°E 32.1'  
14" MAPLE (CLMP 4) S05°E 63.1'  
3" MAPLE S45°W 47.5'

DROVE 1/2"x 43" GALV PIPE  
W/RLS CAP & SET CED POST W/LOC  
TAG.  
4" ASH N50°W 44.1'  
9" OAK N40°E 62.5'  
3" OAK N65°E 45.6'  
3" OAK S05°E 67.3'

Signed by Carl F. Roser 12-14-90 Date

Surveyor's Michigan License No. 17028

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS

