

## APPROVED LAND CORNER

P.A. 345 OF 1990  
MIDLAND COUNTY

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Midland County Remonumentation

483

8/24/00 JRG

For Corners in

Midland

(County)

Located In:

Corner Code#:

## 1. Public Land Survey

T. 15N R. 2W I-1T.        R.       T.        R.       2. Public Controlling  
in SectionS.        T.        R.       S.        T.        R.       

## 3. Miscellaneous

S.        T.        R.       

## Property in Section

S.        T.        R.       4. Lot No.       , Recorded Plat       5. Private Claims       SECTION       STATE OF MICHIGAN  
MIDLAND COUNTY  
REMONUMENTATION & FILED

10/6/2000 10:36:48 AM

SCOTT I. HAINES  
REGISTER OF DEEDS

Register of Deeds Stamp &amp; File Number

I, Mark R. Robison, in a field survey on July 14, 2000, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below.

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

## A. Description of original monument and accessories and/or subsequent restoration:

1832, Wright

Int. N. Bdy 0.55 West of Post

Maple 16" S51°E, 40 LINKS

W. Oak 16" S68°W, 24 LINKS

1980, Mueller, LCRC #534

Fd piece of R.R. Track on end 2' deep

Set T. Iron

N85°E, 35.70 iron &amp; cap

N45°E, 73.0 14" Apple Tree

NNE 111.5 P.P.

1903, Gibbs, CSR

R.R. Iron in center of road

Meas. West 40.16

Meas. South 39.70 (19.72 &amp; 19.98)

## B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Found T-Iron over R.R. Iron in gravel road per 1903 and 1980 surveys. This monument is 4.07 feet South of standard line between I-13 and G-13 of T16N, R2W, and 35.58 feet West of I-13. Accepted R.R. Iron as perpetuation of G.L.O. closing corner (property controlling corner, and set 3/4" pipe in Mon. Box) and set I-1 4.07 feet North on standard line. Set standard Midland County monument and Mon. Box and witnessed I-1 as set on the Standard Township line. Meas. East 2650.45 to J-1.

## C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 3/4" x 18" pipe brass cap stamped "Midland County Remon P.S. #27458" in Mon. Box.

Witnesses:

N35°E, 107.24' - N &amp; T in P.P.

N65°E, 70.23' - N &amp; T in North trunk of Twin 18" Apple

N30°W, 37.20' - N &amp; T in 18" Willow

N10°W, 147.86' - N &amp; T in P.P.

South, 4.07' - G.L.O. closing corner

East, 35.58' - I-13, T16N, R2W



Signed by

Mark R. Robison

Date

9-15-2000Surveyor's Michigan License No. 27458

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975  
REVISED JAN., 1983