

Land Corner Recordation Certificate
Attachment B to 2016 Annual Grant Agreement
 Authority: MCL 54.205 and R54.202

This form is **ONLY** for corners filed under the 2016 State Survey and Remonumentation Grant Agreement

Filing Requirement: MCL 54.268(2)(a), 54.268(2)(d), 54.201 – 54.210d and 2016 State Survey and Remonumentation Grant Agreement

Notes:

- No more than two Original Public Land Survey Corners can be recorded on this certificate
- If a corner reported hereon is common to two or more survey townships, each Town, Range and Corner Code for the corner may be identified on this certificate
- If a corner reported hereon is common to two or more counties, each county may be identified on this certificate and a copy of this certificate filed with the Register of Deeds in each county

For corner(s) in: Midland County

Edenville Twp.

Corner Type	Survey Township		Corner Code	
Original Public Land Survey Corner	T	16N R 1W	D9	1
• MCL 54.202(g)	T	R		2
• MCL 54.262(g)	T	R		3
	T	R		4
				5
Property Controlling Corner	S	T R		6
• MCL 54.202(i)	S	T R		7
• MCL 54.262(h)	S	T R		8
	S	T R		9
Protracted Public Land Survey Corner	T	R		10
• MCL 54.202(k)	T	R		11
• MCL 54.262(i)	T	R		12
	T	R		13

	A	B	C	D	E	F	G	H	I	J	K	L	M	
1														1
2	6			5		4		3		2		1		2
3														3
4	7			8		9		10		11		12		4
5														5
6	18			17		16		15		14		13		6
7														7
8	19			20		21		22		23		24		8
9				●										9
10	30			29		28		27		26		25		10
11														11
12	31			32		33		34		35		36		12
13														13
	A	B	C	D	E	F	G	H	I	J	K	L	M	

Part A: Corner(s) History

D9 – 1832 – GLO – H. Parke – Set ¼ post

- 1) Birch 11" N6°E 30 L.
- 2) Maple 17" S18°W 20 L.

- 1852 – GLO Dependent Resurvey – A. Burt – Old ¼ Corner

- 3) B. Ash 6" S42°E 24 L.
- 4) W. Pine 24" N82°W 24 L.

Part B: Surveyor's Report on Perpetuation or Monumentation of Corner(s)

D9 – ¼ Corner common to Section 20 & 29, T16N, R1W – Fd. remains of 24" White Pine Stump that is believed to be witness #4; only one found within a reasonable distance. Dug 3"± diameter area in sand in wet and dry area. No stake remains found. Set stamped 4" DNR Aluminum Cap on 1" x 4' long galvanized iron pipe at record bearing and distance from WPS (#4). Measured East 141'± [153' – Enter wetland C. SE & NW – GLO] to edge of grass and brush marsh and East 367'± [384' – Leave wetland C. SE & NW – GLO] to edge of grass and brush marsh. Measured grid bearing and distance to set ½" x 24" rebar in remains of 25"± WPS to ground of N89°10'35"W 666.88' [N89°55'W 665.28' – W. Pine 25" dia. – GLO] and N89°15'58"W 2637.73' [N89°55'W 2651.88' – GLO] to 'C9'. DNR Monument accepted as a careful and faithful perpetuation of the position of the original corner.

