

Land Corner Recordation Certificate
Attachment B to 2016 Annual Grant Agreement
Authority: MCL 54.205 and R54.202

This form is ONLY for corners filed under the 2016 State Survey and Remonumentation Grant Agreement

Filing Requirement: MCL 54.268(2)(a), 54.268(2)(d), 54.201 – 54.210d and 2016 State Survey and Remonumentation Grant Agreement

Notes:

- No more than two Original Public Land Survey Corners can be recorded on this certificate
- If a corner reported hereon is common to two or more survey townships, each Town, Range and Corner Code for the corner may be identified on this certificate
- If a corner reported hereon is common to two or more counties, each county may be identified on this certificate and a copy of this certificate filed with the Register of Deeds in each county

For corner(s) in: Midland County Edenville Township

Corner Type Survey Township Corner Code

Original Public Land Survey Corner

MCL 54.202(g)

MCL 54.262(g)

Property Controlling Corner

MCL 54.202(i)

MCL 54.262(h)

Protracted Public Land Survey Corner

MCL 54.202(k)

MCL 54.262(i)

16N 1W B8

1	A	B	C	D	E	F	G	H	I	J	K	L	M	1
2	6			5		4		3		2		1		2
3														3
4	7			8		9		10		11		12		4
5														5
6	18			17		16		15		14		13		6
7														7
8	19			20		21		22		23		24		8
9														9
10	30			29		28		27		26		25		10
11														11
12	31			32		33		34		35		36		12
13														13
	A	B	C	D	E	F	G	H	I	J	K	L	M	

Part A: Corner(s) History

B8 – 1901 – CSR L. 1, p. 92 – F. J. Gibbs – Set W. Oak post – Sec. 19 Petition Survey.
1) Pine stump N82½°W 29½ L.

Part B: Surveyor's Report on Perpetuation or Monumentation of Corner(s)

B8 – Center ¼ Corner Section 19, T16N, R1W – Found 8"± Cedar anchor post for fences north, south, and west. Dug around post but no evidence of wood stake found. Found remains of pine stump to ground for witness #1. Set stamped 2" aluminum cap on 5/8" x 34" rebar at record bearing and distance from witness #1. Corner falls on N. side of noted fence corner anchor post. 2" aluminum cap accepted as the best available evidence of the position of the corner.

Part C: Field Evidence of Perpetuation or Monumentation of Corner(s)

B8 – C ¼ corner Sec. 19, T16N, R1W  
Stamped 2" aluminum cap on 5/8" x 34" rebar.  
North 20.04' to set nail & tag in W. side 8" R. Maple  
N62°E 34.47' to set nail & tag in NW side twin 5" & 8" W. Oak  
East 6.89' to set nail & tag in S. side 6" R. Maple with scribed 'XBT'  
S19°E 15.85' to set nail & tag in NE side 9" W. Oak with scribed 'XBT'  
S59°W 15.98' to set nail & tag in NW side 7" R. Maple  
Added Blue Composite Post with location tag 1' E.

Date of Observation	Latitude	Longitude	Datum and Adjustment Year	Epoch Date
May 26, 2015	N43°45'48.0404"	W84°28'38.3800"	NAD83(2011)	2010

Set 3 Control Points with baselines from 2 Local OPUS base stations. Ran closed traverse from control points to 'B8' and back and adjusted by least squares.

I, Craig W. McVean, in a field survey on May 26, 2015, certify under the requirements of the State Survey and Remonumentation Act, 1990 PA 345, MCL 54.261 to 54.279, and the Corner Recordation Act, 1970 PA 74, MCL 54.201 to 54.210d, that the corner(s) identified and described hereon has been perpetuated or monumented as described in Parts A, B, and C above, pursuant to the laws and rules of the State of Michigan.

Craig W. McVean

Craig W. McVean

12/7/2016

Date

Professional Surveyor's License No.: 39088

Department of Natural Resources, 8015 Mackinaw Trail, Cadillac, MI 49601



I, Brian D. Ferguson, state that the corner(s) identified and described hereon and perpetuated or monumented as described in Parts A, B, and C above was presented to and reviewed by the Peer Review Group on Aug. 3, 2016, and is accepted for filing in the Midland County Remonumentation Program.

Brian D. Ferguson

Brian D. Ferguson

Date

Professional Surveyor's License No.: 26454