Land Corner Recordation Certificate

Authority: 1970 PA 74, MCL 54.205

Surveyor's Name: Craig W. McVean					Field Survey Date: September 20, 2016								
For corner(s) in: Midland				County									
Original Public Land Survey Corner					Corner Code								
S	т		R										
s	Т		R			- 1 ^A	BC	DE	FC	3 H I	JI	K L I	M ₁
S	Т		R			,		5		1	į	1	2
s	Т		R			2	6			3			1
Property Controlling Corner					Corner Code	3	7	8	9	10	11	12	3
S	т		R			- 5							5
S	T		R		gs =	- 6	- 18	-17	1 <mark>6</mark>	- 15	- 14 -	- 13 -	6
S	т	202 - 70	R			- 7							7
s	T		R			8	19	20	21	22	23	24	8
Property Corner					Corner Code	9	19	20	21	22	23	2,4	9
S	27 T	16N	R	1W	5	- 10	30	29	28	27	26	25	10
S	27 T	16N	R	1W	6	-11			-				⊣ 11
S	Т		R			12	3 1	- 32 -	- 33 -	- 34	35 -	- 36 -	
S	т		R			-56	-1-	JZ	3				13
Protracted Public Land Survey Corner					Corner Code	13	4 B (CDI	E F (G H	IJ	K L	M
s		·	_ R _			_							
S			_ R .			_							
S	7		_ R .			_							
S	1	<u> </u>	_ R			_							

Part A: Corner History

<u>5</u> – CN 1/16 corner Section 27.

No history

<u>6</u> – NE 1/16 corner Section 27. - No history

Part B: Surveyor's Report on Perpetuation, Restoration, Reestablishment, or Monumentation of Corner

5 - CN 1/16 corner Section 27, T16N, R1W. Set 2" aluminum cap on 5/8" x 34" long rebar per standard BLM procedure. Base of a rotted off steel fence post for cable south and east is S59°W 1.1' <u>6</u> - NE 1/16 corner Section 27, T16N, R1W. Set 2" aluminum cap on 5/8" x 34" long rebar per standard BLM procedure. Corner falls in wildlife flooding area. Also found a ¾" iron pipe N68°E 3.41' of corner '6'. Found no record of this pipe so did not accept as corner.

Part C: Field Evidence of Perpetuation or Monumentation of Corner

<u>5</u> – CN 1/16 corner Section 27, T16N, R1W.

Stamped 2" aluminum cap on 5/8" x 34" long rebar.

Set blue composite post with location tag 1' southeast S85°W 28.34' to set nail & tag in south side 8" Oak S22°E 8.92' to set nail & tag in east side triple 8" Red Maple

N52°E 41.88' to set nail & tag in northwest side 8" Red Maple

N23°W 44.07' to set nail & tag in west side triple 3" Oak

6 - NE 1/16 corner Section 27, T16N, R1W.

Stamped 2" aluminum cap on 5/8" x 34" long rebar.

Set blue composite post with location tag 1' southeast N05°E 189.56' to set nail & tag in east side 11" W. Oak S39°E 106.92' to set nail & tag in northeast side 20" Cottonwood

N64°W 132.26' to set nail & tag in south side 11" Red Maple

N68°E 3.41' to found 34" iron pipe



Craig W. McVean

Professional Surveyor's License No.:

٥.

39088

Prepared By:

Craig W. McVean

Michigan Dept. of Natural Resources

8015 Mackinaw Trail

Cadillac, Michigan 49601