REMON CORNER A-7, EDENVILLE TWP. LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970 For corners in Midland Located in: Corner Code # (County) 1. Public Land Survey T 16N R 1W SURVEY & 2. Property Controlling T in Section s Т Miscellaneous Ţ R Property in Sec. R SECTION Lot No. Recorded Plat 5. Private Claims

STATE OF MICHIGAN **MIDLAND COUNTY** REMONUMENTATION & FILED

12/28/2000 8:44:27 AM

SCOTT I. HAINES REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, <u>RODNEY CLAYPOOL</u>, in a field survey on <u>June 11</u>, 19<u>99</u>, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned on lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
- Corner common to Sections 18 and 19 on West townline A-7

Survey by Glo, 1830, set post Survey by F. Gibbs, 1900, post with stone around Survey by MDOT, 1937, used corner Survey by J. Jones, 1994, found 1/2" rod in monument box raised with 3/4" pipe

- Κ н D F 6 2 3 4 8 Q 10 12 5 15 14 13 18 17 16 6 7 24 8 19 20 21 23 9 30 29 28 27 26 25 10 11 31 32 33 35 36 12 13
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Corner common to Sections 18 and 19 on West townline A-7
- Found 3/4" pipe in monument box at position per surveys by MDOT and J. Jones



- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- A-7 Corner common to Sections 18 and 19 on West townline

Replaced 3/4" pipe with 5/8" rod and brass cap stamped Midland Co. Remon Cor. PS 29241 and is accepted as the best available evidence of the position of the original corner.

S 55 Deg, 47.11', chiseled "+" on top of East end headwall N 75 Deg W, 53.06', chiseled "+" on top of West end headwall N 60 Deg E, 58.70', spike in guardrail post S 45 Deg E, 78.04', railroad spike in power pole (BM #410) South 5.60', Warren Twp. corner (GLO calls for 8 links 5.28')

Signed by_ Surveyor's Michigan License No. 29241

12-26-00 Date

Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971

Revised May 14, 1971 Revised Jan., 1983

A CONTRACTOR OF THE PROPERTY O APPROVED LAND CORNER P.A. 345 OF 1990 MIDLAND COUNTY