REMON CORNER M-12, WARREN TWP. LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

549

For co Midlar	mers in			STATE OF MICHIGAN	
	(County)	Located in:	Corner Code #	KIDLAND COUNTY REMONUMENTATION & FILED	
1. Pul	blic Land Survey	<u>T 16N R 2W</u>	<u>M-12</u>		
		TR TR	<u> </u>	12/28/2000 8:44:27 AM	
in S	perty Controlling Section cellaneous	STR	SURVEY & ONUMENTATION FEB 2 3 2001	SCOTT I. HAINES REGISTER OF DEEDS	
Property in Sec. S T R				Register of Deeds Stamp & File Number	
4. Lot No, Recorded Plat SECTION A B C D E F G H I J K L					
i, RODNEY CLAYPOOL, in a field survey on June 23, 1999, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned on lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, re-established, monumented, re-monumented, recovered, found as expressed below:				3 4 7 8 9 10 11 12 5 5 18 17 16 15 14 13 7	
NOTE	Not more than 2 correcorded on this cer	mers, all in the same town a rtificate.	and range, may be	8 19 20 21 22 23 24 9 30 29 28 27 26 25 -	
A. Description of original monument and accessories and/or subsequent restoration:					
M-12	14 corner for Section 3			Wille.	
	Survey by Glo, 1830's Survey by MDOT, 194	i, set post I1, did not find comer		RODNEY D. CLAYPOOL	
B. Description of corner evidence found and/or method applied in restoring or reestablis			hing corner:		
M-12	1/4 corner for Section 3	6 on East townline		hing corner:	
	Set 5/8" rod and brass	s cap at midpoint on straight lin	e between M-11 and M-13		
. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:					
M-12	% corner for Section 36 on East townline				
	Set 5/8" rod and brass cap stamped Midland Co. Remon Cor. PS 29241 at midpoint on a straight line between M-11 and M-13 and is accepted as the best available evidence of the position of the accepted corner.				
	N 45 Deg W, 98.65', n N 60 Deg E, 94.94', na	nail and plastic disk in 10" Elm nail and plastic disk in 8" Elm ail and plastic disk in power pol nail and plastic disk in 6" Pine Twp. corner A-12	ie .	,	
			!		
Signed by Roding a Clargery Date 1226.00					
	Surveyor's Michigan Licerse No. 29241 Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971				
Revised May 14, 1971 Revised Jan., 1983					

不是我们的 1. 10 mm and 1. 10 mm an APPROVED LAND CORNER P.A. 345 OF 1990 MIDLAND COUNTY