

FILE DO NOT MAIL

SURVEY &  
REMONUMENTATION  
LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

WAYNE  
(County)

Located in: Brownstown  
Township

Corner Code #

1. Public Land Survey T 5S R 10E K-4  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_  
2. Property Controlling S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
in Section S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
3. Miscellaneous S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
Property in Sec. S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

MAR 17 1998

SECTION

Compliance with  
ACT 345, P.A. 1990

APPROVED ON: 12-1-97 *JD*  
WAYNE COUNTY REMONUMENTATION  
PEER GROUP COMMITTEE  
Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, Randy Kolehouse, in a field survey on December 2 19 96,  
do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970, the corner points mentioned  
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the  
current manual of survey instructions of the United States Department of the interior, Bureau of Land  
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5  
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a  
Court of Law; established, re-established, monumented, re-monumented, recovered, found as  
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

K-4	1817	G.L.O.	Fletcher	Notes	Post	
	1930's	WPA Notes	N/A	Section Map and Ties	Iron	\$4.00 REMONUMENTATION
	N/A	W.C.R.C.	N/A	Witness Record	Iron	
	1976	Cert. Survey	Arthurs #11358	L. 20025 P. 574	Iron Pipe Stake	
	1976	Cert. Survey	Arthurs #11358	L. 19873 P. 380	Iron Pipe Stake	\$7.00 REED
	1978	Survey	Magee #14926	N/A	N/A	
	1979	Cert. Survey	Arthurs #11358	L. 20551 P. 937-938	Iron Pipe Stake	
	1983	L.C.R.C.	Zbikowski #21586	L. 21659 P. 210	1" Iron Pipe	
	1983	Cert. Survey	Zbikowski #21586	L. 21666 P. 319	1" Iron Pipe	

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

K-4 Found a 1/2" iron pipe 7.3' North and 0.5' West of fence corner, fences running N-S & W per witnesses in Cert. Survey L. 20025 P. 574 and L.C.R.C. L. 21659 P. 210. This corner calculates to be 7.7' North and 0.4' West of the location of K-4 using the WPA Survey of Section of Section 12. The iron found per Cert. Surveys and L.C.R.C. in Part A was found in 1976 by Arthurs and used ever since without any history for the accuracy of its location. I decided to reset this corner at the location as shown by the WPA Surveys or 7.7' South and 0.4' East of the iron found. Prorated our measured distance between K-3 and K-5 to establish the North-South position and used WPA angle at K-4 to establish the East-West position. This position checks with WCRC witness (R= NE 40.4' to 2" Oak; M= N30E 39.54' to PK in SW side 40" Oak) and with Magee (Metro Parks) distance to K-3 (R= 2609.95'; M= 2610.51').

Measure North from Reset Corner to K-3 2610.51' (WPA = 2610.24') (G.L.O. = 2640.0') (Magee = 2609.95')  
Measure South from Reset Corner to K-5 2603.87' (WPA = 2603.60') (G.L.O. = 2640.0')  
Angle at K-4 180° 06' 40" (WPA = 180° 06' 40")

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-4 Set a 4" x 36" concrete monument with a 1/2" rebar and a 2" diameter aluminum cap stamped "Wayne Co. Remon. #25854."

P.K. Nail in SW Face 40" Oak N 30° E 39.54'  
P.K. Nail in W Face 12" Oak N 62° E 19.20'  
P.K. Nail in S Face 15" Oak East 44.05'  
P.K. Nail in E Face Fence Post N 85° W 1.05'

\*+ on E Rim G.V.&W. S 70° W 65.95'  
P.K. Nail in N Side 15" Oak N 50° W 31.73'  
1/2" ID Pipe N 06° E 7.70'

The selected location is accepted by the Contractor and is generally accepted by professional  
surveyors as the best available evidence of the position of the original corner.

Signed by Randy J. Kolehouse Date 12/16/97  
Surveyor's Michigan License No. 25854

