

SURVEY &  
REMONUMENTATION

FEB 13 1998

SECTION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A., 1970

For corners in

MONROE (58)  
(County)

Located In:

Corner Code #

WHITEFORD TWP.

1. Public Land Survey

T8S R6E

K-4

T R

T R

T R

2. Property Controlling  
in Section

S T R

S T R

3. Miscellaneous  
Property in Sec.

S T R

S T R

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

**1997 REMONUMENTATION PROGRAM CORNER**

I, George B. Warnke, Jr., in a field survey on September - December, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by decree of a Court of Law and / or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

**A. Description of original monument and accessories and/or subsequent restoration:**

1820 GLO, Joseph Wampler - Surveyor, set the 1/2 mile post from which a W. Oak 19 ins. dia. bears N30E 9 lks. dis. & a Hickory 21 ins. dia. bears N63W 43 lks. dis.

1964 Michigan State Highway Department Witness Card notes East 1/4 cor. Sec. 11 - set ackerman bolt - witnesses: N25E 64.02 to a 25" Walnut / N55W 68.50 to a 16" Spruce / S25E 53.23 to a 19" Maple

1965 Michigan State Highway Department Witness Card notes 1/4 Cor. To Sec. No. 11 & 12 - boat spike in monument box - witnesses: N27E 25" Walnut 64.02' / S48W power pole 46.76' / S36E 18" Hickory 87.46'

1993 G.B. Warnke recorded LCRC, Liber 3, Page 298, using 3/4" iron pin in mon. box - witnesses are the same as in Section C

**B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:**

9/1997, G.B. Warnke crew found large bolt or boat spike or iron pin in concrete in existing monument box being 1 1/2 feet north of the centerline joint of concrete for St. Anthony road (old M-151).

**RATIFIED BY PEER GROUP, PA 345 OF 1990, MONROE COUNTY, MICHIGAN, DATE 10/14/1997, COUNTY REP.** [Signature]

12/18/1997, G.B. Warnke crew jackhammered around existing pin to remove some concrete and attached plastic remonumentation cap to found pin in existing monument box.

**C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:**

Attached yellow plastic remonumentation cap to found 3/4" iron pin in existing monument box and is accepted as the best available evidence of the position of the original corner.

Witnesses: South 45° West 46.75 feet to found M.S.H.D. nail & tag in northwest face of utility pole

North 30° West 49.78 feet to found nail & shiner in southwest face of guy pole

North 45° East 41.49 feet to found nail & shiner in westerly face of telephone pole

South 50° East 123.0 feet to northwest corner of brick chimney

South 55° East 19.90 feet to "+" in sta. 133+00

Signed by

Surveyor's Michigan License No. 19474

Date December 19, 1997



APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1998  
REVISED MAY 14, 1998  
REVISED JAN. 1, 1999  
REVISED OCT. 1, 1999