

SURVEY & REMONUMENTATION

FEB 13 1998

SECTION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A., 1970

For corners in

MONROE (58)

(County)

Located In:

Corner Code #

WHITEFORD TWP.

T8S R6E  
T R  
T R  
T R  
S T R  
S T R  
S T R  
S T R

L-3

1. Public Land Survey  
2. Property Controlling in Section  
3. Miscellaneous Property in Sec.

REGISTER OF DEEDS  
MONROE COUNTY, MICH

RECEIVED FOR RECORD  
97 DEC 30 PM 3:38

Register of Deeds Stamp & File Number

4. Lot No. Recorded Plat

5. Private Claims

1997 REMONUMENTATION PROGRAM CORNER

I, George B. Warnke, Jr., in a field survey on November 25, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by decree of a Court of Law and / or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:  
1820 GLO, Joseph Wampler, corrected the line between Secs. No. 1 & 12 - set the 1/4 sec. Post at average dis. from which a W. Oak 9 ins. dia. bears S41E 35 lks. dis. & a W. Oak 14 ins. dia. bears N80W 30 lks. dis.  
1973 G.B. Warnke surveys - Fd. 1. Pin  
1974 Case & Fleck survey - stone  
1976 G.B. Warnke survey - stone  
1988 G.B. Warnke survey - found stone  
1989 G.B. Warnke survey & LCRC, Liber 3, Page 68 - found stone 8" deep (laid 3 R.R. spikes along side of stone)  
1993 G.B. Warnke survey - set 1" x 15" capped iron pipe over found stone in place of found nail & washer over stone  
1996 G.B. Warnke survey - found 1" x 15" iron pipe over stone
- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:  
In 1996, G.B. Warnke found 1" x 15" iron pipe over stone in Samaria Road being a gravel surface.

RATIFIED BY PEER GROUP, PA 345 OF 1990, MONROE COUNTY, MICHIGAN, DATE 11/18/1997, COUNTY REP.

11/25/1997, G.B. Warnke dug a 2 feet diameter hole and found 1" x 15" pipe with ref. Cap over stone. Dug out 8" x 11" x 20" long limestone. Dug to 4 foot with no other evidence found. Set 1/4" x 18" rod at 3.5 feet and 2 railroad spikes in bottom of hole on east and west side of rod. Set 1" x 36" pipe with brass remonumentation cap in monument box and set broken pieces of stone around pipe at 15" deep.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:  
Set 1" x 36" pipe with brass remonumentation cap in monument box to replace found 1" x 15" iron pipe over stone and is accepted as the best available evidence of the position of the original corner. Witnesses:  
North 8' to centerline of gravel road  
South 5.19' to found iron pin  
S60W 41.75' to PK nail in northerly face of telephone pole  
North 41.59' to PK nail in southerly face of electric pole

Signed by

Surveyor's Michigan License No. 19474



Date December 16, 1997