

SURVEY & REMONUMENTATION

APR 28 1995

LIBER 1810 PAGE 48

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MUSKEGON
(County)

Located in:

Corner Code #

1. Public Land Survey

T 9N R 15W

E-12

2. Property Controlling
in Section

S T R

3. Miscellaneous

S T R

Property in Sec.

S T R

4. Lot No. , Recorded Plat

5. Private Claims

Register of Deeds Stamp & File Number

STATE OF MICHIGAN
COUNTY OF MUSKEGON
RECEIVED FOR RECORD
1994 DEC 27 AM 11:42
Caleb C. Custer
REGISTER OF DEEDS

A 1555

I, STEPHEN V. VALLIER, in a field survey on DECEMBER, 19 1994

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

1837 GLO SET 1/4 POST

S 54° W 11 LINKS 15" HEMLOCK

N 86° E 11 LINKS 8" HEMLOCK

1957 C.F. LEWANDOWSKI

FOUND IRON BOX

SW CORNER - W 1/4 CORNER SECTION 33, 2643.67'

1981 C.F. LEWANDOWSKI RE-SET 1/2" REROD IN POSITIO
OF MISSING BAR

N 25° E 42.44'

S 15° W 29.51'

S 75° W 42.10'

S 80° E 19.64'

18" ASH

3" OAK

18" PINE

14" ASH

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND 1/2" X 18" ROD-ACCEPTED POSITION DUE TO DISTANCE CONFIRMATION TO SW CORNER SECTION 2640.10'

Aug 2, 1994

POSITION OF SAID
RECORDED CORNER
REVIEWED & RATIFIED
BY MUSKEGON COUNTY
PEER GROUP IN ACCORDANCE
WITH P.A. 345, OF 1990

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

SET 2 3/4" X 30" CAST IRON MONUMENT WITH COUNTY SURVEY CAP-REPLACED 1/2" X 18" ROD

S 15° W 29.51'

S 73° E 19.64'

N 25° E 42.44'

S 75° W 42.10'

S 16° E 34.90'

N 62° W 54.40'

NAIL E. SIDE 6" OAK

NAIL N. SIDE 14" ASH

NAIL SE SIDE 18" ASH

NAIL N. SIDE 14" R. PINE

NAIL E. SIDE 8" OAK

NAIL N. SIDE 12" R. PINE

Signed by

Date

Surveyor's Michigan License No. 28428

Surveyor
No.
28428

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 15
REVISED MAY 14, 15
REVISED JAN., 15