

1883

LIB 1744 FILE 564

STATE OF MICHIGAN  
COUNTY OF MUSKEGON  
REGISTER OF DEEDS

1993 DEC 29 PM 4:04

0000

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

*Carrie Carter*  
REGISTER OF DEEDS

For corners in

MUSKEGON

(County)

Located In:

Corner Code //

1. Public Land Survey T 9N R 15W I-6  
T R  
T R  
T R
2. Property Controlling S T R  
in Section S T R
3. Miscellaneous S T R  
Property in Sec. S T R
4. Lot No. , Recorded Plat
5. Private Claims

Register of Deeds Stamp & File Number

I, STEPHEN V. VALLIER in a field survey on NOVEMBER 24, 1993, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO CORNER SET BY J. MULLETT, APR. 30, 1837  
S 38°W S 59°E  
13 LINKS 10 LINKS  
10" BEECH 10" HEMLOCK  
IRON PIPE MUSKEGON CO. ROAD COMM. 1955  
NO WITNESSES

1 1/2" IRON PIPE IN MONUMENT BOX  
J. CAMPBELL, NOV. 1979. REC. LBR. 1188  
PG. 209  
NW SE  
52.35' 66.85'  
G. POLE LGT. POLE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND 1/2" X 18" IRON PIPE OVER 1 1/4" IRON PIPE

(BELIEVE LBR. 1188, PG. 209 INCORRECTLY RECORDED WRONG CORNER)

HISTORICAL USAGE, DOCUMENTATION & EVIDENCE OF CORNER LOCATION REVIEWED AND RATIFIED BY MUSKEGON COUNTY PEER GROUP NOV. 2, 1993

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

SET 2 3/4" X 20" CAST IRON MONUMENT WITH CO. SURVEY CAP (REPLACED 1/2" X 18" IRON PIPE)

N 72°W	N 24°W	N 47°E	N 73°E	S 56°E	S 52°W
69.73'	101.09'	187.41'	108.80'	112.06'	75.34'
14" CHERRY	8" POPLAR	44" MAP.	12" R. PINE	10" J. PINE	14" TW. CHERRY
CLUMP (SET	(SET NAIL	(SET NAIL	(SET NAIL	(SET NAIL	(SET NAIL
NAIL S'LY SIDE)	NE'LY SIDE)	NW'LY SIDE)	SW'LY SIDE)	S'LY SIDE)	SW'LY SIDE)

Signed by

STEPHEN V. VALLIER

Surveyor's Michigan License No.

28428

Date

Dec 28, 1993