REMONUMENTATION

MAR 0 6 1998

1 REP 2052 PAGE 580

Common	Con
STATE OF MICHIC COUNTY OF MISSE RECENSES	DAN ISC.

SECTION

For corners in

expressed below:

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

E97	DEC	30		3:	10
Car			و الماريخ المريخ المريخ ال	. 7	Sauce 22. 4

Muskegon (County)	Located in:	116	Code #			Ca	ezec HEOIST	二 (TR 0	ing Paga	ine Tre	نرياس
1. Public Land Survey	Aiso CON 16 T 10N R 171 T R T	W Corner	nder	,	•				· · · · · ·	U.	
2. Property Controlling in Section3. Miscellaneous Property in Sec.	T R S T R S T R S T R S T R			Register	of De	eds Sta	amp &	File	Nun	nber	
79	Recorded Plat			A	B C	D E	F G	H 3-	J	<u>к</u>	L N
do hereby certify that under re	in a field survey on requirements of P.A. 74, Michigar a in conformance with regulation	n P.A. of 1970, the co	orner points mentione	d 6	7-18	-17	- 9	-10- -15-		1	-12-

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

Description of original monument and accessories and/or subsequent restoration:

Meander corner on the Line between Sections 25 T10N R17W and 30 T10N R16W and the South shore of Muskegon Lake

Post set by GLO Surveyors in 1837; B Oak 11" S11°W 40L and B Oak 10" S57°E 25L 16.69 Chains (1101.54') North of 1/4 Corner

MCRC, 1950's Witness Map and Current Witness Book do not cover this area.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 2" Pipe over 1" Iron Bar

Have records of M M Buck, F F Smith, C F Lewandoski and R W VanRiper using this corner. Accepted corner based on historical usage and documentation

POSITION OF SAID RECORDED CORNER REVIEWED & RATIFIED BY MUSKEGON COUNTY PEER GROUP IN ACCORDANCE WITH P.A. 345, OF 1990

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 2 3/4" Cast Iron Monument with County Survey Cap

N 46° E 55.531 Set Spike in N side of 12" Tree

N 81° E 60.911 Set Spike in N side of Twin 22" Poplar

S 85° E Set Spike in N side of 18" Tree Set Spike in E side of 12" Maple 77.291 S 04° W 139.52'

N 49° W 75.951

Set Spike in W side of Triple 20" Poplar Set Spike in W side of 16" Tree N 03° W 56.541



Signed by Laft W.	Vu	13.
Surveyor's Michigan License No	169	946

•	Dec.	26,	1997
	200.	-0,	4.77.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975