

MAR 2 1 1997

Surveyor's Michigan License No. ___28428

For corners in

LIBER 1952 PAGE 577

COMMISSION

LIBER LUUCPAGED / / STATE OF MICH. COUNTY OF MUSKEGEN COUNTY OF MUSKEGEN LAND CORNER RECORDATION CERTIFICATE PECEIVED FOR RECORD Filing Requirement of Act 74, Mich. P.A. 1970 1976 DEC 27 PM 1: 10

	(County)	Located In:	Corner Code ##	Carin Carter
1.	Public Land Survey	T <u>10N</u> R 17W T R	H-2	A 1821
		T R T R		, , ,
	Property Controlling in Section Miscellaneous	S T R S T R S T R		Register of Deeds Stamp & File Number
J.	Property in Sec.	S T R		Register of Deeds Stamp & File Number
		Recorded Plat		
J .	Tivate Claims		. ,	2 6 5 - 4 - 2 - 1 -
l,	Stephen V. Vallier, P.	S, in a field survey on NOV	EMBER 8, 19 96	tioned 5
in li curi Mar	ines 1 and 2 above were rent manual of survey ins nagement or by a decree	equirements of P.A. 74, Michigan P.S. in conformance with regulations a structions of the United States Depart of Law and/or that the conwith the rules of the Michigan Board	and rules therefore as required artment of the Interior, Bureau of ner points mentioned in lines 3, 4	in the f Land 7 and 5 8 13 20 21 22 23 24
Cou exp	irt of Law; established, ressed below:	re-established, monumented, re	-monumented, recovered, four	nd as
NO.	TE: Not more than 4 on this certificat	corners, all in the same town : e.	and range, may be recorded	11 12 31 32 34 35 36
Α.	Description of origina	al monument and accessories a	nd/or subsequent restoration	13 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	CORNER NOT SET 1950's - M.C.R.C I	NO DESCRIPTION OF MONU NORTHEAST SOUTHEAST	93.25' 30" 62.00' TEL	BLACK OAK LEPHONE POLE
	1050 HNDECORD	NORTHWEST	• •	MAPLE NER TO SOUTH QUARTER 2624.32'
	1930 - ONNECOND			
₿	Description: of corner	evidence found and/or method	d applied in restoring or rees	tablishing corner:
	THIS CORNER LIES	ON PIPE ION OF CORNER HISTORICA S 25' SOUTH AND 30' WEST ER OF SECTION IS MONUMI	OF COMPUTED CENTER	OF SECTION RON ROD STEPHEN VALLIER
	٠.	REVIEWEI BY MUSK	D CORNER D & RATIFIED EGON COUNTY	Land Surveyor No. 28428
		PEER GRO WITH P.A	DUP IN ACCORDANCE A. 345, OF 1990	CAND S.
C.	Description: of: monur	ment for corner and accessorie	s established to perpetuate I	locating the position of the corner:
	REPLACED 1" X 30	" IRON PIPE WITH 2 3/4" X 30	" CAST IRON MONUMENT	T WITH COUNTY SURVEY CAP.
	NORTH 54° WEST NORTH 39° EAST NORTH 83° EAST SOUTH 79° EAST SOUTH 54° WEST SOUTH 84° WEST	60.28' 16" (37.68' UTIL 45.63' 29" (40.67' 6 -10	OAK LITY POLE	FOUND SPIKE IN NORTHEAST SIDE FOUND SPIKE IN NORTHWEST SIDE FOUND SPIKE IN SOUTH SIDE FOUND SPIKE IN SOUTHWEST SIDE FOUND SPIKE IN NORTHWEST SIDE FOUND SPIKE IN SOUTH SIDE

A1821

24 1996

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 197 REVISED MAY 14, 197 REVISED JAN., 198