## SURVEY & REMONUMENTATION

MAR 2 1 1997

LIREP 1952 PAGE 804

A1837

STATE OF MICHIGAN COUNTY OF MUSKEGON RECEIVED FOR EECORD

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

1996 DEC 30 AH 8: 47

For corners in			MAR DEG 20 191 Or of t	
MUSKEGON		Located In:	Corner Code ##	1 - 12 - 12
	(County)		3011101 300c 447	Carrie Carter
1.	Public Land Survey	T 10N R 17W	· J-5	news fra Of Degos
		T R		
		T R		
		T R	•	
2.	Property Controlling	S T R		
	in Section	S T R		
3.	Miscellaneous	S T R		Register of Deeds Stamp & File Number
	Property in Sec.	S T R	· ·	megister of Deeds Stamp & File Hulliber
	• • •			
				•

	•														
4. Loi	No, R	ecorded Plat		· · · · · · · · · · · · · · · · · · ·		а	c	מ	, E F		н	1.	ıĸ		
5. Pri	vate Claims			44.4.*		Ť	Ť	Ť	Π	Ť	Ϋ	Ť	Π̈́	Ť	_
					3	- 6- 		5	1		- 3 		2:		_
Ste	ephen V. Vallier, P.S.	in a field aumou as	October 30	96	4	_	-	8	9 	+	-10 	+1	╎┤	 12	<u>.</u>
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the								17-	16		-15	<del> </del>	4	— 13 — 13	<u> </u>
current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a						-19-		20-	-21	+	-22-	+-;	3-		
Court o			mented, re-monumented,	•	10	-30-		<del> </del>	28	$\perp$	27_	<u></u>			
express												1			

Description of original monument and accessories and/or subsequent restoration:

1837 CORNER SET BY G.L.O.

SOUTH 4° EAST

28" LINKS 8" BROWN ASH

NORTH 5° EAST

18" LINKS

12" HEMLOCK

1950's M. BUCK SURVEY

WEST 2706.2' TO SECTION CORNER EAST 2698.0' TO SECTION CORNER

F.F. SMITH

RECORDED L.C.R.C LIBER 1036, PAGE 230

FOUND IRON ROD IN MONUMENT BOX

C.F. LEWENDOWSKI

FOUND AND RECORDED L.C.R.C LIBER 1322, PAGE 620

1/2" IRON ON TOP OF 5/8" PIPE

RESET WITH 2 3/4" X 30" CAST IRON MONUMENT WITH COUNTY SURVEYOR CAP Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND 2 3/4" X 30" CAST IRON MONUMENT WITH COUNTY SURVEYOR CAP WITNESSES CHECK WITH LIBER 1322, PAGE 620 CORNER IS 4.0' EAST OF SINGLE PROPORTIONATE MEASURE ACCEPTED POSITION OF CORNER BY HISTORICAL USAGE AND DOCUMENTATION OF RECORD. WEST 2705.98 TO SECTION CORNER 1-5 EAST 2698.0 TO SECTION CORNER K-5

POSITION OF SAID RECORDED CORNER REVIEWED & RATIFIED BY MUSKEGON COUNTY PEER GROUP IN ACCORDANCE WITH P.A. 345, OF 1990

monument for corner and accessories established to perpetuate locating the position of the corner: Description &

FOUND 2 3/4" X 30" CAST IRON MONUMENT WITH COUNTY SURVEYOR CAP.

SOUTH 25.48°

**POWER POLE** 

FOUND SPIKE

WEST 2705.98' TO SECTION CORNER I-5

EAST 2698.04 TO SECTION CORNER K-5

Signed by Surveyor's Michigan License No.

28428

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 197 REVISED MAY 14, 1971 REVISED JAN., 198:

TEPHEN

VALLIER Land

Surveyor No.

28428

LAND

11837