4. Lot No. _____, Recorded Plat _____

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICH	GAN
COUNTY OF MUSK	ርሳር ክ
RECEIVED	

corners	

5. Private Claims __

expressed below:

Muskegon (County)	Located In:	Corner Code =##	mas eeu 29 FH (2: 57
Public Land Survey	т <u>11N</u> в 15W Т 8	F-2	Cassin Consta
	T R		
	T R		t
2. Property Controlling	1 S T R		
in Section	S T R .		
3. Miscellaneous	S T R		Register of Deeds Stamp & File Number
Property in Sec.	S R		

, 19 <u>93</u> I, Donald G. Sandel in a field survey on November 17 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
 - Corner not set by GLO survey.
 - No MCRC witnesses on record for this corner (1950's). (2)
 - Muskegon County witness book witnesses: NE 11" White Oak 35.5'; NW 12" White Oak (3)26'.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - (1) Set 4" x 20" County survey monument by intersection of quarter lines method for determining center of section.
- Historical usage, documentation, and evidence of corner location reviewed and ratified by Muskegon County Peer Group, November 16, 1993.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 4" x 20" cast iron "County Survey" monument witnessed as follows: North, set, nail E side, 7" White Oak, 2.63' S 60 deg. W, set, nail S side, 12" Red Oak, 22.62

S 03 deg. W, set, nail E side, 12" Oak, 32.48

S 60 deg. E, set, nail SW side, 11" Oak, 12.03'
N 32 deg. E, set, nail S side, 16" White Oak, 19.40'
S 42 deg. E, set, nail W side, 17" Red Oak, 41.38'

Signed by Ronald G. Vandel	Date 29 December 1993
Surveyor's Michigan License No. 25870	FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983