

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 43-44 N.R. 23 W


Marquette COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 4 and 33

CORNER MONUMENT 1" Pipe with 4" Brass Cap

DATE MONUMENT PLACED AND WITNESSED 6/5/61

WITNESSES TO CORNER....10" Cedar (1/4s NBT) S 30° E 24 1/2 Links



13" B. Ash (1/4s NBT) N 53° E 13 1/2 Links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from two Cedar stumps bearing N 28° E, 31 Links and N 37° W, 31 Links. No identifying mark on either stump which were cut recently. B.T.'s were evident before being cut. Corner found by Arne Metsa, District Forester.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE July 21, 1961  
REGISTERED LAND SURVEYOR  
Billy D. Buckler