

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES  
LAND CORNER RECORD


Marquette COUNTY  
T 43 N R 24W

DESCRIPTION OF CORNER Section corners for sections  $\frac{6}{5}$   
 $\frac{7}{8}$

CORNER MONUMENT 1" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 8-28-72 F. J. Bray

WITNESSES TO CORNER..... 6" R. Maple ( S5) (NBT) N47°E, 10.0'



11" Balsam ( S7) (NBT) S63°W, 5.6'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from cedar and hemlock Stumps in rotted condition.

Overgrowth of faces and axe mark visible. Stumps check good for bearings

and distances as noted in original notes.

SURVEYOR'S SEAL

DISTRIBUTION:

Forestry Division, Lansing

SIGNED

Frank J. Bray  
REGISTERED LAND SURVEYOR  
Frank J. Bray

DATE

11-17-72