

✓
STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES
LAND CORNER RECORD


Marquette COUNTY
T 43 N R 24 W

DESCRIPTION OF CORNER Witness corner to meander corner for sections 31/32

CORNER MONUMENT 1" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 9/12/69, F. J. Bray

WITNESSES TO CORNER..... 12" Cedar (BT) N 89° E, 24½ links



9" Elm (W.C.) (BT) S 30° W, 48½ links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed on line between section corner in river and 1/4 corner to south. Corner is 2.25 chains south of corner in river.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

Frank J. Bray
REGISTERED LAND SURVEYOR
Frank J. Bray

DATE 10/2/69

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68