

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

B.M.C.
8-26-80

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____	T. <u>44</u> N. S., R. <u>23</u> E. W.	<u>J-3, K-3</u>
2. PROPERTY CONTROLL- ING IN SECTION_____	T. _____ N. S., R. _____ E. W.	_____
3. MISCELLANEOUS PROPERTY IN SECTION_____	T. _____ N. S., R. _____ E. W.	_____
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND
FILING NUMBER _____

I, David B. Babbitt do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on July 17 1980, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____ 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

- J-3 South $\frac{1}{4}$ corner - Section 2.
- K-3 S.E. section corner - Section 2; Wood Post, Hemlock 18" - N75°W - 12 lks.
Do. 14" - S73°E - 16 lks.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- J-3 Set M.P.O.L. between the S.E. and S.W. section corners of Section 2.
- K-3 Found remains of very large rotted hemlock stump for N.W. O.B.T. and fragments of rotted hemlock in place for the S.E. O.B.T. No marks on them, but this position fits the stream calls 75 lks. south and 3.00 chs. west and measurements are reasonable to corners in all four directions.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- J-3 1" pipe, 4" aluminum cap; 5" Cedar - N8°E - 4.8'; 4" B. Ash - N61°E - 8.7'; 8" Cedar - S5°W - 12.7'; 9" Cedar - S83°W - 6.3'.
- K-3 1" pipe, 4" aluminum cap; 5" Balsam - S21°E - 5.8'; 13" Hemlock - S45°W - 8.8'; 7" Hemlock - N28°E - 8.2'; 12" Cedar - N22°W - 30.5'.

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____ (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY David B. Babbitt DATE 8-26-80
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. 21558