· Lesson the second

Surveyor's Michigan License No.

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

1998 DEC 16 PM 3: 20

For corners in		riling Require	ement of A	ict /4, Mich. P.A	A. 1970		•		
MARQUET	TE	Located In:	Corr	ner Code #		0	/.		
(County)	16.	Localeu III.	Con	ier Coue #		Value	TER OF DE	Janke	W
(Odanty)						REGIST	TER OF DE	EDS 0	1
1. Public Land Surv	ev -	Γ <u>45N</u> R 25W	D/F -	13 M.C. <u>#</u> 5					₫,
TT CONTO LONG OUT	•		D/E	1 M.C. (#1)					
	_	<u> 44N</u> R <u>25W</u>	DIE -	1 IVI.C. (#1)	1				
	_	<u>ΓR</u>							
		<u> </u>		····					
2. Property Control	ling S	Γ R							
in Section	s ⁻	Γ R					TO O		
Miscellaneous	s ⁻	Γ <u>. </u>				LIBER	\mathbf{R}^2	PAGE	(3)
Property in Sec.	S	ΓR							• •
					Reg	ister of Dee	ds Stamp	& File N	lumbei
4. Lot No	. Recorded Pla	t							
						CDE	F G H	IJ	K L
				,					
I. GERALD W. CAR	I SON in	a field curvey on	N#AV	E TLI 10 00	2 - 6	 5	43		 1 -
I, <u>GERALD W. CARLSON</u> , in a field survey on <u>MAY</u> 5 TH , 19 98 , do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points									
mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as							. 910-	,	l_
required in the current manual of current instructions of the United Chatas Department of the Interior						ĭ	ĺĺľ	1 7	1
Bureau of Land Management or by a decree of a Court of Law and/or that the corner points								1	++
mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of							16 15	14	13-
Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented,									
recovered, found as exp		uit of Lave, establish	icu, i c c stat	maneu, monument	· []				
rocovorou, rodina do oxp	100000 0010111				819	20	21 22	1-23-	24-
NOTE: Not more the	an 2 corners all in	the same town an	d range ms	w he recorded	9		 		
on this certif		i the same town an	a range, me	ly be recorded	10-30	29	28 27	26_	25
on this certi	icate.				1 1	171		اً ا]
A Description of ari	ainal				11				
A. Description of ori	yınaı monument a Sor common to Co	nd accessories and/	or subseque	ent restoration:	12 31	- 32-	3334-	3,5	36-
D/E-13: Meander Corr	iei common to Se	Cuon 32, 145N-R2	ovv and Sec	tion 5, 144N-KZ	<u> </u>				
No Date: M.C.R.C. Go Department of Conser 20" Cedar S 4" S. Maple N	overnment Corner vation Brass Cap 04E, 37 L 27W, 15 L	Index Book for Sec (7/18/50) on West 16" Balsan	side of Esc n S21\	anaba River. Refe W, 04 L	renced by:				ı
	rth side of Sectior / District Forester	5, T44N-R25W, it Metsa, of Gwinn.	also indica When I saw This corne	tes the corner mo the Corner, one or was set on July	nument as a 1 of the original	" Iron Pipe ' B.T.'s, a ce	w/ 4" Bras dar was st	s Cap.	ily
B. Description of cor D/E-13: 1998: No orig cap, stamped to ident well after monument	ginal corner evider ify the corner, Pip	ice found. Found ar e was leaning East,	nd accepted 1.0' high.	a 1 1/2" O.D. Ird Bearings and dist	on Pipe with 4" ances to remai	ning 2 refer	ences che	cked ve	tion ery
Established new refere	monument in a ve t 1998". Monume 87W, 36.09 (C ences:	rtical position using	recorded bound. Measo	earings and distar	nces from 2 rea ails and washe	naining witi	nesses. St g reference	es:	
23" Hemlock S	57W, 43.61'			12" Maple	N07W,	11.28'			
Green Steel Sign Post	w/ Yellow Survey	Marker Sign S4	8W, !	5.10'		يججح	OF HIS		
Note: Bearing trees ha and stamped B.T. Tag		outt, and side nail b	lazes, d.h. ı	neasuring nails,		GA BOOK	CALL ST	N. A.	
			RATIFIEL P.A. 345	O BY PEER GRO OF 1990	OUP	C/	RALD W. ARLSON JRVEYOR No.	*	
			DATE	Nov 2, 199	8	No.	24589		ſ

MAA 1 8 1999

D/E - 13 M.C.: PART A CONTINUED

1982: A Certificate of Survey by Gerald W. Carlson P.S. #24589 for the Minatome Corporation (No Liber and page given) indicates the corner as a monumented meander corner on the West side of the Escanaba River. Distance N89-28'-34"E, 217.80' to the S.E. Corner of Section 32;, Distance S8 28'-34"W, 2419.56' to the South 1/4 Corner of Section 32. No accessories given.

1982: An LCRC recorded by Gerald W. Carlson P.S. #24589 in L. 5, RC Pg. 38, indicates that the corner was a D.N.R. Monument set by Dean DeLamater on 7/18/50. Recorded references:

20" Cedar 4" S. Maple

S04E, N27W, 37 L 15 L 16"

Balsam

Carlson found an Iron Pipe w/aluminum cap, +/- 9' West of river, and Cedar stump at correct bearing and distance for Cedar B.T.. He set a 2"X2"X4"

\$21W,

04 L

stake alongside pipe. Referenced by: 12" Cedar

N88W,

6" Maple (in cluster)

N2OW,

9.90

9.90

8" Balsam

\$40E,

36.05 24.46'

20" Cedar

S03E.

25.85' (DeLamater NBT)

1983: A Certificate of Survey recorded by Gerald W. Carlson P.S.#24589 in L. 001, SM pp. 440, 441, and 443 indicates the corner as a fd. DNR Monument and remains of Cedar stump at correct bearing and distance for original Cedar B.T.. Referenced by:

12" Cedar 8" Balsam N88W, S40E,

36.051 24.46

6" Maple (in cluster) 20" Cedar

N20W, S03E.

25.85' (DeLamater NBT)