SURVEY & REMONUMENTATION

FEB 21 2001

SECTION

For corners in

5. Private Claims

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

MARQUE	TE (COUNTY
RECEIVED	HIGA FOR	.R RECORD

200 DEC 12 PM 2: 29

Pateicie RFGISTER	A.	More	len.
RFGISTFR	OF	DEEDS	por

MARQUETTE (County)	Located In:	Corner Code #
1. Public Land Survey	T <u>45N</u> R <u>25W</u> TR TR TR	C-7
2. Property Controlling in Section	S T R S T R	
Miscellaneous Property in Sec.	S T R S T R	
4. Lot No Re	acorded Plat	

LIBER R2 PAGE 246 Register of Deeds Stamp & File Number

, <u>2000</u> , do GERALD W. CARLSON , in a field survey on July 6 hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

C-7: Corner common to Sections 17, 18, 19, & 20. 1852: Martin M. Hall's original subdivision survey notes describe the corner monument as

a Cedar post referenced by: 15L

N45E.

1931: C.C.I. Coordinate Sheet indicates the Northeast quarter corner of Section 19 as

North 2640.18' and a East 36.15' from the 0, 0 Point.

34" Hemlock

RATIFIED BY PEER GROUP P.A. 345 OF 1990

1958: Marquette County Road Commission Notes indicate the Northeast corner of Section 19 as a 1/2" Iron Pin. No references given.

S51W.

261

1981: A Land Corner Recordation Certificate recorded in L. 4, RC page 68, by Glenn C. Van Neste, L.S. 27464 indicates Southeast corner of Section a found bent 1 1/2" Iron Pin referenced by: 5" 2.351 Jack Pine S30W, 19.47'

10" Jack Pine S49E, 9" White Pine

16" Cedar

NO9W. 19.72'

(This corner certificate appears to be recorded incorrectly.)

1988: Sundberg, Carlson and Associates, Inc. tied into a 1" Iron Pin North and West of County Road EES and traverse work for the Assessor's Plat of Princeton.

1989; Corner shown on the recorded Plat of the Assessor's Plat of Princeton. No corner monument or accessories given.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C-7: 2000: No original corner evidence found. Found and accepted a 1 1/2" axle shaft. Based upon the measurements and long standing use, this axle shaft appears to be the same monument as the 1" pin referenced in part A.

Checked Line Call: South, 1, 24 chains (81.81), leave swamp, course NW. We measured 82.01

Checked Line Call: South, 7.24 chains (477.8'), enter swamp, course NW. We measured 475.2'.

Checked Line Call: North, 1.96 chains (129.4'), top of hill 150', course SE. We measured 129.4'.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-7: 2000: Replaced the 1 ½" axle shaft with a 2 3/8" O.D. aluminum pipe capped with a 3 1/4" diameter aluminum tablet Marquette County Survey Monument stamped to identify the comer. Monument is 0.9' above ground.

24" Maple N15W, 138.41 16" N67E. Maple

Maple

N59E. 12.95

Referenced by:

9.86

16" Twin Maple

20.00 N88E.

Green Steel Sign Post w/ Yellow Survey Marker Sign

Distance East 2632,51', distance West 2620,79'.

3.651

Note: Bearing trees have painted face, butt, and side nail blazes, d.h. measuring nails, and stamped B.T. Tags affixed.

T45N-R25W

Corner Search Sheet

2000035

TE OF MICH GFRALD W CARLSON SURVEYOR No. 24589

Signed by	Duold	Wallson

Date 12-6