SURVEY & REMONUMENTATION

FEB 2 1 2001

MARQUETTE COUNTY MICHIGAN RECEIVED FOR RECORD

SE	CT	ION

2mg DEC 12 DM 2: 29

SECTION	LAND CO	ORNER RECORDA	TION CERTIFICA	TEZW ULL IZ PA Z. Z.
_	Filing R	equirement of Act	74, Mich. P.A. 19	70
For corners in MARQUETTE (County)	Located In:	Corner	Code #	Patricia d. Monlay REGISTER OF DEEDS
1. Public Land Survey	T <u>45N</u> R <u>25</u> T R T R	W G-	7	·
Property Controlling in Section Miscellaneous Property in Sec.	T R S T R S T R S T R S T R S T R			LIBER ${f R}2$ PAGE 250 Register of Deeds Stamp & File Number
			<u></u>	Trograms or Books of the
4. Lot No, Re				
5. Private Claims				A B C D E F G H I J K L I
I, <u>GERALD W. CARLSON</u> hereby state that under requirementioned in lines 1 and 2 a required in the current manu Interior, Bureau of Land Managmentioned in lines 3, 4 and 5 Land Surveyors or by a Decreoovered, found as expressed	bove were in conformance al of survey instructions of ement or by a decree of a above were in conformance eree of a Court of Law;	chigan P.A. of 1970, e with regulations and of the United States Court of Law and/or the e with the rules of the	the corner points I rules therefore as Department of the lat the corner points Michigan Board of	2 6 5 4 3 2 1 1 3 4 7 8 9 10 11 12 5 6 18 17 16 15 14 13 7 8 19 20 21 22 23 24
•			. h.a. unnanudad	9
NOTE: Not more than 2 on this certificate.	orners, all in the same t	own and range, may	be recorded	10-30-29-28-27-26-25
A. Description of original G-7: Corner common to Se 1852:Martin M. Hall's origi	monument and accessor	<u>.</u>		11 12 31 32 33 34 35 36 13 RATIFIED BY PEER GROUP
Yellow Birch post reference 14" Spruce Pine N24W.	d by: 23L 14"	Spruce Pine SO	8E, 17L	P.A. 345 OF 1990
No Date: County Survey ap Section 21. Distance West	parently by Charles Cun 2676.5'. Distance Sout	h 2620.6'.		
1943: Marquette County R No Date: Marquette Count Referenced by:	oad Commission Notes i y Road Commission Not	indicates the Souther les indicate the North	ast corner of Section neast corner of Sect	n 16 as an Iron Pipe. ion 21 as an 1 1/4" Iron Peg.
5" Jack Pine S70E, 10" Jack Pine S65W			0W, 16.37' 85W, 83.16'	
1978: Certificate of Survey Iron Peg. Distance East 26	by Gordie Frasier and A 32.29'. Referenced by:	Associates, William R : Same as MCRC wit	. Donnan indicates nesses and as those	the Southwest corner of Section 15, 1 1/4" e listed below.
1979: Land Corner Records	1 1/4" Iron Peg. Refere	nced by:		L. 1 RC page 315 indicates the Southwest
5" Jack Pine S70E, 10" Jack Pine S65W			OW, 16.37' 35W, 83.16'	
	vey, recorded in Liber 1:	SM, page 696, by Ro		RLS #19616 indicates the Southwest corner
C. Description of monum G-7: 2000: Replaced the 1	ner evidence found. Founds. 5.25' ent for corner and acces " x 4.2' solid iron rod w	nd and accepted a 1' sories established to ith a 2 3/8" O.D. alu	" x 4.2' solid iron ro perpetuate locating	of 18" above ground. If the position of the corner: If with a 3 1/4" diameter aluminum tablet
Marquette County Survey Referenced by: 7" W. Pine N79E,		dentify the corner. N W. Pine S15E,	9.17'	above ground.
5" W. Pine S72W, Green Steel Sign Post w/ \ Distance North 2618.45', Note: Bearing trees have p and stamped B.T. Tags aff	18,34' 9" 'ellow Survey Marker Sidistance East 2633.01', ainted face, butt, and si	gn S88W, distance West 2676 de nail blazes, d.h. m	25.25' (Donnan 3.86' 3.54'. neasuring nails,	GERALD W. CARLSON SURVEYOR No. 24589
И	De Carlson		Date	1881 11308
Signed by				GAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
Surveyor's Michigan Licen	se No24589	· · · · · · · · · · · · · · · · · · ·	funni approved by Michi	GAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAM. 29, 1971 REVISED MAY, 14,1975 REVISED JAN., 1983 REVISED OCT., 1995