

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

✓

LAND CORNER RECORD

T. 45N N.R. 27W


Marquette COUNTY

DESCRIPTION OF CORNER $\frac{1}{4}$ cor. bet. Secs. 27-34

CORNER MONUMENT 1" pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 8/15/66

WITNESSES TO CORNER..... 7" Jack Pine ($\frac{1}{4}$ S NBT) North 38.1'



9" Jack Pine ($\frac{1}{4}$ S NBT) S25°W 25.5'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced at site of 14" Jack Pine Stub, remains of the original corner tree; with one jack pine bearing S30°E 17 links. Tree down and in poor condition with some evidence of both upper and lower faces.

Corner lies 1 chain north of woods road.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 1/11/67
REGISTERED LAND SURVEYOR