

For corners in

County

Corner Code #1

T 45N R27W

F2

S4

1

— — — — —

**S**

T

15

Recorded Plat

1. Keith Sackett, \_\_\_\_\_, in a field survey on \_\_\_\_\_, October 25, \_\_\_\_\_, 19 89,  
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned  
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the  
current manual of survey instructions of the United States Department of the Interior, Bureau of Land  
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5  
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a  
Court of Law, established, re-established, monumented, re-monumented, recovered, found as  
expressed below:

**A Description of original monument and accessories and/or subsequent restoration:**

F2

8

12

15

Not set on original survey nor subsequently, apparently.

F2

8

12

15

Established midway and on  
line.

**f2**

8

12

15

Set 1" ID x 32" iron pipe w/4" aluminum cap.

20" r. pine N14E 36.3' 1/16s,

BT

20" r. pine N18W 40.1' 1/16s,

BT

4" w. pine S49E 5.0' 1/16s, BT

Robert L. Bell

Date \_\_\_\_\_

August 27, 1990

19006

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 20, 1971  
REVISED MAY 14, 1975  
REVISED JAN. 1983