

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 45. NR. 29. W

Marquette COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 11 and 12

DESCRIPTION OF CORNER MONUMENT 1" Iron Pipe with 4" Brass Cap,

WITNESSES TO CORNER 9" Oak (1/4s NBT) S 10° E 3 Links

8" Oak (1/4s NBT) N 10° E 56 Links

7" Oak (1/4s NBT) N 85° E 20 1/2 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED. This corner was replaced from two stumps. One to S E has face and axe
marks burned badly. One to N W is stump bottom. Both in proper position.

Corner was placed and witnessed July 16, 1959.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 4/28/60
REGISTERED LAND SURVEYOR
Billy D. Buckler