

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Marquette

(County)

Located In:

Corner Code #

1. Public Land Survey

T 45N R 29W L12

T R

T R

T R

2. Property Controlling
in Section

S 36 T 45N R 29W 9

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

Dec 12 2002

I, Stephan J. Szyszkoski, in a field survey on Dec 12 2002, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35			
13													

A. Description of original monument and accessories and/or subsequent restoration:
(L12) Center of Section 36. Not established in the original survey. Local foresters have run some approximate lines in this area.
(9-Sec. 36) East 1/16 corner, Section 36. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(L12) Established the corner at the intersection of straight lines connecting opposite quarter corners. From the position thus established, I found an iron pin set by an unknown party S54W 5.3' distant.
(9-Sec. 36) Established the corner midway and on a straight line between Quarter corner 1320.97' east and Center of Section 1320.97' west.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(L12) Set 1"IDx32" I.pipe with 4" alum.
MDNR cap. Blazed, scribed, and set
measuring nails in:

9" Tamarack East 10.75' "C1/4 BT"

10" Spruce S24E 39.78' do

7" Spruce S80W 18.98' do

7" Tamarack N57W 16.75' do

Set sq'd cedar post adjacent. Bearings
are magnetic. Distances are to nail
with tag.

(9) Set 1"IDx32" I.pipe with 4" alum.
MDNR cap. Blazed, scribed, and set
measuring nails in:

7" B.Spruce N69E 10.88' "1/16S BT"

4" Poplar S52E 12.94' do

4" B.Spruce S47W 17.95' do

2" B.Spruce N58W 8.12' do

Set sq'd cedar post adjacent. Bearings
are magnetic. Distances are to nail
with tag.



Signed by Stephan J. Szyszkoski

Surveyor's Michigan License No. 33986

Date 12/19/02

For the Michigan Department of Natural Resources - Office of Land and Facilities

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1995