

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 46 NR. 25 E.

----- Marquette ----- COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 16, 17, 20, 21 -----

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass cap -----

WITNESSES TO CORNER 10" Spruce - N 52 E - 30 Links -----

10" Balsam - S 40 E - 34 Links -----

8" Spruce - N 55 W - 108 Links -----

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR  
RESTORED.

This corner was found by Forestry Division survey crew, while working in this area. Wooden Post in place, corner had been located by others. Two original B.T.'s, badly rotted, in place.

Corner was placed and witnessed July 10, 1951.

SURVEYORS SEAL

SIGNED Dean C. Seela Miller DATE 7/25/51 -  
REGISTERED LAND SURVEYOR