

SURVEY & REMONUMENTATION

APR 28 1995

COMMISSION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

MARQUETTE COUNTY
MICHIGAN
RECEIVED FOR RECORD

1994 DEC 29 PM 1:56

For corners in
Marquette
(County)

Located In:

Corner Code #

46N 25W

K-12

- | | | | |
|-------------------------|---|---|---|
| 1. Public Land Survey | T | R | |
| | T | R | |
| | T | R | |
| | T | R | |
| 2. Property Controlling | S | T | R |
| in Section | S | T | R |
| 3. Miscellaneous | S | T | R |
| Property in Sec. | S | T | R |

RATIFIED BY PEER GROUP
P.A. 345 OF 1990

DATE Sept 26, 1994

LIBER

1 PAGE 231

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

Michael Mileski

September 94

I, _____, in a field survey on _____, 19____, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

K-12; East One-Quarter Corner Section 35;

Originally established during U.S. Survey conducted by Wm. Ives, D.S. for Douglass Houghton, D.S. in 1845 and monumented with a wood post witnessed by a Spruce Pine 4 S19°E 8 lks. and a Spruce Pine 4 N65°W 12 lks.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

K-12; East One-Quarter Corner Section 35;

Found no evidence of U.S. monumentation or accessories. Reestablished corner midway and on line between the southeast corner of section 35 and the northeast corner of section 35.



State Plane Coordinates:

Grid System - NAD 83

Zone Number - 2111 Michigan North

Units - International Feet

Y = 567939.76499

X = 26149032.34367

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-12; East One-Quarter Corner Section 35;

Set 3/4" x 24" iron rod with 3" aluminum cap appropriately stamped as to location.

SE Cor. Pump Hse. Bldg.

Set 60d spike

W/side

13" Jack Pine

N65°E 149.00'

Set 60d spike

SE/side

10" Jack Pine

S24°E 188.11'

SE Cor. Bldg. #308

S44°W 205.67'

N11°W 42.81'

All of the above new bearing trees marked with upper and lower face blazes and scribed "NBT".

Signed by Michael Mileski Date 21 Nov 1994

Surveyor's Michigan License No. 39091