

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 45-46 N.R. 27-28


Marquette COUNTY

DESCRIPTION OF CORNER Section Corner common to Secs. 1-6-36-31; also a Township Corner

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 5/1/64

WITNESSES TO CORNER..... 8" Jackpine (S31 NBT) 157°E 62 Lks.



8" Jackpine (S1 NBT) S38°W 14 Lks.

7" Jackpine (S36 NBT) N31°W 59 Lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was replaced at a $1\frac{1}{2}$ " Iron Pipe set by unknown person. Found a $5/8$ " Iron Pin in ground. Found an old Fence Corner bearing S55°W 76 Links from Corner. No evidence of Original Witnesses.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 8/4/1964
REGISTERED LAND SURVEYOR