CONS. 4047 REV. 10/60

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T. 46 N.R. 271/

	Marquette	COUNTY
DESCRIPTION OF CORNER	Section Corner common to Sections 27-28-33-34	
CORNER MONUMENT	ln Pipe with 4" Fluminum Cap.	
DATE MONUMENT PLACED AND	WITHESSED	
WITHESSES TO CORNER	9" E. Cak (S28 TDT) N 13°W 35.5'	
N	10" B. Cak (\$34 NET) \$100 4.21	
33	9" B. Oak (S33 NBT) S790W 42.31	
CIRCLE CORNER REGISTERED	AND	

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced from two W. Pine witnesses, bearing S56°W 37 links and N3°M 26 links. Both stumps badly burned with few marks remaining.

SURVEYOR'S SEAL

SIENED Billy IX Buckler DATE 10/25/67

REGISTERED LAND SURVEYOR