

# LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

(MARQUETTE COUNTY)

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 46 N. R. 29 W.	#L-7
2. PROPERTY CONTROLLING IN SECTION 24	T. 46 N. R. 29 W.	#1
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. S. R. E. W.	
4. LOT NO.	RECORDED PLAT	
5. PRIVATE CLAIMS		

REGISTER OF DEEDS STAMP AND  
FILING NUMBER

I, Arthur O. Enger, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on November 5, 1979, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_, 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Corner L-7 (1/4 corner between Sections 13 & 24, T46N, R29W):

Spruce post (Not found. No subsequent monuments found.)  
Spruce 5 N70W 12 (Not found. No subsequent accessories found.)  
Cedar 9 S84E 15 (Not found. No subsequent accessories found.)

Corner 1 (West 1/16 corner between Sections 13 & 24, T46N, R29W)

Not established in original survey and apparently only by approximation subsequently.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Corner L-7: Restored on line between Section Corners 40.162 ch. to E and to W.

Corner 1: Established on line between Sec. Cor. 20.081 ch. W and 1/4 cor. 20.081 ch. E.  
Found an old 3" x 3" x 5' squared cedar post S40E 11.7 ft., set by unknown persons many years ago; however, as no 1/4 cor. was found on this section line it is doubtful whether this post was set from anything other than a magnetic compass line.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner L-7: 1" I.D. x 36" iron pipe with 3 3/4" aluminum cap.  
White Birch 12 N86°W (mag.) 9.1 ft. "1/4S, NBT"  
Tamarack 6 S46°E (mag.) 19.3 ft. "1/4S, NBT"  
Declination 2° 35' West.

Corner 1: 1" I.D. x 36" iron pipe with 3 3/4" aluminum cap.  
Tamarack 5 N88°E (mag.) 10.0 ft. "1/16S, BT"  
Tamarack 4 N32°W (mag.) 8.2 ft. "1/16S, BT"  
Declination 2° 25' West.

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_

(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

APPROVED AND SIGNED BY Arthur O. Enger DATE March 7, 1980  
CHIEF OF SURVEY PARTY  
MICHIGAN REGISTERED LAND SURVEYOR

Arthur O. Enger

Michigan Department of Natural Resources

SURVEYOR'S MICHIGAN REGISTRATION NO. 13581