

1995 DEC 27 AM 7:44

JOB NUMBER: 95053

SHEET NO. : 1-622

APR 01 1996

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MARQUETTE
(County)

COMMISSION

Located in:

Corner Code #

Patricia L. Mosley
REGISTER OF DEEDS

1. Public Land Survey

T 47N

R 26W

M-7

T 47N

R 25W

A-7

T

R

T

R

2. Property Controlling
in Section

S

T

R

S

T

R

3. Miscellaneous

S

T

R

S

T

R

Property in Section

LIBER

1 PAGE 240

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

GERALD W. CARLSON, in a field survey on Wednesday, November 8, 1995

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

M-7: Section Corner common to Sections 13 and 24, T47N-R26W established by proportionate measurement. Referenced by: and Sections 18 and 19, T47N-R25W, 1844: William A. Burt's 8" J. Pine N76W, 32.34' original survey notes describe the corner monument as a wood 10" W. Birch N56E, 23.76' post referenced by: 1951: MCRC F.B. #651 indicates the corner and references as recorded above in Record of Surveys Book #1, Pg. 131. 1989: The corner is indicated on an Easement Description Map for Wisconsin Electric recorded by Sundberg, Carlson, and Associates in L. 130, MR Pg. 756, 131, recorded by Michigan Department of Conservation Forestry Division (Dean C. De La Mater, RLS #05778). Corner was

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1995: Found and accepted a 1 1/4" dia. galvanized pipe, 1.0' above ground, with a 4" dia. Michigan Department of Conservation brass cap, stamped to identify the corner. Monument is 12' +/- East of a two-track Rd.. Distance North is 5254.01', and Distance South is 2616.93'.

RATIFIED BY PEER GROUP
P.A. 345 OF 1990Larry J. Bussome
DATE 11/6/95

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1995: Rewitnessed existing Michigan Department of Conservation Monument using double headed nails set in:

14" Spruce	N13W, 56.57'
13" W. Pine	N54E, 33.83'
16" W. Pine	N79E, 68.42'
12" J. Pine	S52E, 24.34'
Green Steel Sign Post w/Yellow Survey Marker Sign	North, 2.0'

Note: Bearing Trees were face and butt blazed, painted, and had bearing tree tags affixed.

Bk. 9, pp. 57-58.



Signed by

Gerald W. Carlson

Date

12-15-95

Surveyor's Michigan License No.

24589

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 23, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983