## SURVEY & REMONUMENTATION

FEB 21 2001

## SECTION

Surveyor's Michigan License No.\_

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

	r denres
-MARQUEFTE	COUNTY
MICHIG	AH
RECEIVED FO	IR RECORD

200 DEC 18 PM 12: 44

Patricis	s G.	More	lem
Patricia REGISTO	R OF	DEEDS	1º

24589 SURVEYOR

MARQUETTE (County)	Located In:	Corner Code #	Σ <sup>i</sup> :	atricia d. M. RFGISTER OF DEE	nley) DS O J
1. Public Land Survey	T <u>47N</u> R <u>27W</u> TR TR	G-4			1
Property Controlling in Section     Miscellaneous Property in Sec.	TR S T R S T R S T R S T R		Register	LIBER ${f R}2$ P	
4. Lot No, Re 5. Private Claims	corded Plat		- A B C	DEFGH	IJĸ
hereby state that under requirementioned in lines 1 and 2 a required in the current manual Bureau of Land Management mentioned in lines 3, 4 and 5	irements of P.A. 74, Michigan bove were in conformance with of survey instructions of the Unite or by a decree of a Court of above were in conformance with ree of a Court of Law; establis	May 9 TH, 2000, do P.A. of 1970, the corner points regulations and rules therefore as distates Department of the Interior, Law and/or that the corner points the rules of the Michigan Board of shed, re-established, monumented,	1 2 6 3 4 7 5 6 18 7 8 19 19 19 19 19 19 19 19 19 19 19 19 19	-8 - 9 - 10 - 15 - 15 - 20 - 21 - 22 - 21	111414141414
NOTE: Not more than 2 con this certificate.	orners, all in the same town a	nd range, may be recorded	10 30 11	29 28 27	26
G-4: Quarter corner common 1848: John Burt's original surronwood quarter section program 20" Sugar S65E.  1891: Cummings survey reand distance 2624.66' Sou Section 9 to be in the Lake 1891: Cummings survey, Sourth.  1893: Corner is shown on the No Date: The CCI coordinate W20810.69.  Part A continued on reverse B. Description of corner er G-4: 2000: No original corn Measured found references	subdivision survey notes descript referenced by:  10L 24" Yellow corded page 222 indicates the th and 1243.4' to the sixteent Superior Mine Shaft house. ection 10 shows the West qua the Superior Terminal Railway e list indicates the coordinates side. vidence found and/or method and er evidence found. Found and	d/or subsequent restoration: ibe the corner monument as a se w Birch N29W, 34L East quarter corner of Section 9 th corner North. This document arter corner. Distance 2624.7' S Company Map with a building or s for the Quarter Corner common applied in restoring or reestablish d accepted a ½" rebar with P.S. 2.7', bearing checks reasonably w	DATE also indicates the South and 1243. Autline next to it. In to Sections 9 a sing corner:	4' to the sixteenth and 10 as S7557.9	b ner of
P.K. Nail in SW side of Ligh Nail in Power Pole		105.07' 47.60'	wen.		
G-4: 2000: Replaced the 1/2	" P.S. #25836 & 30091 iron irvey Monument stamped to ic 137.73' P. Pole 156.66' L. Pole sories besides those given. ellow Survey Marker Sign	established to perpetuate locatin with a 2 3/8" O.D. aluminum pip dentify the corner. Monument is \$64E, 50.75' N58W, 105.13' North, 0.69'	e capped with a	a 3 1/4" diameter a	ıluminum i by:
	inted face, butt, and side nail Search Sheet 2000035	blazes, d.h. measuring nails, and	stamped B.T. 7	age Tredit MICH	64,4
Signed by Hers	Quetalser	Date 12-1	200	CARLSON SURVEYOR No.	1 3 1

## Part A continued:

Ru 1/37

1924: The quarter corner is shown on the recorded plat of Barnum Addition to the City of Ishpeming.

1961: Michigan State Highway Department witness sheet indicates Iron bolt 1" diameter and 30" in length referenced by:

13.74 N60W,

stake S75W,

7.37 stake N25E, 5.27'

No Date: A Survey Sketch of the Northwest corner of Section 10 by E.C.I. indicates a found 1 1/2" Iron Pin:

P.K. in Power Pole \$40W, 74.7'

P.K. in Light Pole N75E, 160.36'. P.K. in Light Pole N60W. 86.97 Southeast Cor. of House N20W, 91.07'

Iron in R.R. Tracks. Distance East 2608.5. Distance North 2489.14.

quarter corner of Section 10 and a distance South 2628.86'.

1979: Land Corner Recordation Certificate recorded in L. 1 RC, page 324 by Charles F. Clark indicates he used CCI coordinates to set a 1/2" X 24"

Capped Rod witnessed by:

Nail in Power Pole S86E, 47.18 Nail in Light Pole N47W. 55.111

Southerly Gate Post N27E, 152.7

1982: East quarter corner of Section 9 is shown on the recorded Assessor's Plat of Barnum Location No. 2. Distance West 1316.6' to the sixteenth corner.

1982: West quarter corner of Section 10 shown on the Assessor's Plat of Excelsior Location recorded by Charles F. Clark, RLS #25836 shows the West

1985: Survey Sketch by Gust Salminen, RLS #11369 recorded in Liber 353 Deeds, page 835 indicates the East quarter corner of Section 9 just East of the Barnum Mine Pit. Distance West 1316.6'.

1985: Land Corner Recordation Certificate recorded in L. 5, page 55 by James Minard, LS# 30091, indicates a set 1/2" Capped Rebar witnessed by:

P.K. Nail in SW side of Light pole N74W, 104.52

P.K. Nail in 3" Poplar 2' South of Fence S18E, '00,88

Nail in Power Pole S86E, 47.18 Centerline of South Gate Post N27E, 152,70'

1987: Certificate of Survey recorded in L. 396, page 588 by Charles F. Clark, RLS #25836 indicates the West quarter corner of Section 10.

1999: A Description Sketch recorded in L. 423, page 770 Alan Pierce, LS #30097 indicates the East quarter corner of Section 9. Distance North 2489.84'.

> **SURVEY &** REMONUMENTATION

> > FEB 21 2001

SECTION