

# SURVEY & REMONUMENTATION

MARQUETTE COUNTY  
MICHIGAN  
RECEIVED FOR RECORD

1994 DEC 28 PM 5:56

JOB NUMBER: 94030  
SHEET NO.: 1-477

APR 28 1995

## LAND CORNER RECORDATION CERTIFICATE

COMMISSION

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MARQUETTE  
(County)

Located In:

Corner Code #

*Patricia A. Mearns*  
REGISTER OF DEEDS

1. Public Land Survey

T 47N R 24W

M-3/4

T R

T R

T R

T R

2. Property Controlling  
in Section

S T R

S T R

3. Miscellaneous  
Property in Sec.

S T R

S T R

#1

LIBER

1 PAGE 148

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, GERALD W. CARLSON, in a field survey on Thursday, December 8, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

### A. Description of original monument and accessories and/or subsequent restoration:

M-3/4: Meander Corner where East Line of Section 12 intersects Lake Superior North of East 1/4 Corner of Section 12.  
1844: William A. Burt's original survey notes describe the corner monument as a wood post referenced by:  
14" Y. Pine S85W, 19 L 10" W. Pine S11E, 54 L

1989: A Certificate of Survey recorded in Liber 001, Pg. 629 by Glen C. Van Neste RLS No. 27464 indicates the Meander Corner is a found 1 3/4" iron pipe referenced by:  
4" Jack Pine, Az 02, 14.90'  
5" W. Pine, Az 82, 10.32'  
NW House Corner Az 138, 80.50'  
16" W. Pine Az 193, 50.58'  
Distance South to East 1/4 Corner listed as 834.34'.

### B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1994: Found and accepted a iron pipe as referenced in Part A above for WCMC.  
Distance South is 834.29'.

### C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1994 - Replaced 1" inside diameter iron pipe with a 2 1/2" diameter aluminum pipe capped with a 3 1/4" diameter tablet Marquette County Survey Monument stamped to identify the corner referenced by nails in:  
5" White Pine N82E 10.10 ft. GCVN NBT  
16" White Pine S12W 50.56 ft. GCVN NBT  
9" Maple S81W 86.19 ft. (Slightly bent East, no blazes or BT tag)  
NW corner of house foundation S42E 80.94 ft. GCVN Accessory  
green steel sign post North 1.00 ft.  
Monument is set 0.3 ft. above ground and is 80 ft. from the waters edge.  
Bk. 5, Pg. 99

RATIFIED BY PEER GROUP  
P.A. 345 OF 1990

*Larry J. Bussone*  
DATE Oct 31, 1994

Signed by Gerald W. Carlson

Date 12-22-94

Surveyor's Michigan License No. 24589

