

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Marquette (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____ T _____ R _____ T _____ R _____	_____ _____ _____
2. Property Controlling in Section	S 20 T 47N R 29W S _____ T _____ R _____ S 20 T 47N R 29W	14 (GCDB 300320) 9
3. Miscellaneous Property in Sec.	S _____ T _____ R _____ S _____ T _____ R _____	(GCDB 260340) _____ _____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 14 06/16/15
9 06/18/15 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(14-Sec. 20) South 1/16 corner between Sections 20 and 21. Not previously monumented.

(9-Sec. 20) Center-East 1/16 corner, Section 20. Not previously monumented.



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(14-Sec. 20) Established the position for the corner midway and on the Section line between Section
corner 1305.76' south and Quarter corner 1305.76' north. The position for the corner falls in a
marsh and is not accessible. Set a Witness corner on the South 1/16 line, 200.00 ft. west of the
corner position.

(9) Established the position for the corner midway and on a straight line between Quarter corner
1334.38' east and the intersection of quarter lines of Section 20 1334.38' west.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(14) Set 1"IDx28" I.pipe with 2" alum. MDNR cap
200.00' west of the corner position for a Witness
Corner.

Set measuring nail with MDNR tag in the side of:
12" R.Pine S03°E 17.7' mrkd "WC BT"
4"x4" treated "stop ahead" signpost S13°W 48.2'
4"x4" treated post S.E. cor. bridge N26°W 60.2'
2" Maple N04°W 17.45' mrkd "X X"
Set cedar post adjacent.
E= 7926985.137 N= 186006.543 (the W.C.)

(9) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
The pipe leans south in rocky ground. The top
center of the cap marks the corner position.
Set measuring nail with MDNR tag in the side of:
6" Sugar N32°E 7.9' mrkd "1/16S BT"
6" Balsam S76°E 12.9' do
8" Balsam S20°E 15.6' do
7" Sugar S81°W 32.1' do
Set cedar post adjacent.
E= 7926645.339 N= 186407.215

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.
Coord. Ref.=NGS PID AA8080: N= 192972.689 m. E= 7925456.741 m.

Signed by Stephan J. Szyszkoski Date 06/23/2015
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division