MAY 2 2 1997

## COMMISSION

COMMISSION		D CORNER RECORDATION CERTI	IFICATE	
For corners in	Fili	ng Requirement of Act 74, Mich. P.A	l. 1970	
MADAITEΦΦΦ	I manto di luc	<b>0</b>	RECORDED 12c. 26 1996	
MARQUETTE (County)	Located In:	Corner Code #	AT 4:30 O'CLOCK P.M.	
1. Dublic Land Com-	- 40x	2011	HBER OF PAGE	
1. Public Land Survey	T_48NR T_47NR	A ATV	Fatricia 4-Montes	
	TR		REGISTER OF DEEDS	
	TR			
Property Controlling     in Section	<u>s TR</u>			
3. Miscellaneous				
Property in Sec.	S T R		A PART 3	
	<u> </u>		Register of Deeds Stamp & File Num	
A Lathle D				
5. Private Claims	rded Plat			
· · · · · · · · · · · · · · · · · · ·			1 B C D E F G H I J K	
			2 - 6 5 4 3 2	
ALAN K. PIERCE		MOVEMBER	3	
requirements of P.A. 74. Michia	, in a field survey on an P.A. of 1970 the com-	NOVEMBER 19 96 do hereby state that under points mentioned in lines 1 and 2 above were	der 4 7 8 9 10 11	
conformance with regulations and	tules therefore as require	of in the current manual of automatical and 2 above were	' <sup>in</sup>	
that the corner points mentioned	finition, bureau of Land M	anagement or by a decree of a Court of Law and	/or 6 18 17 16 15 14	
Codia of Falla Odi 484012 Ol Di	/ A Decree of a Calift A	were in comormance with the rules of the Michiga f Law; established, re-established, monumente	an 7	
recovered, found as expressed be	elow:		8 19 20 21 22 23	
NOTE: Not more than 2 comers, all in the same town and range, may be recorded		9		
on this certificate.		, , , , , , , , , , , , , , , , , , , ,	10 30 29 28 27 36	
			11	
			12 31 32 33 34 35	
			13	
A. Description of original mo	nument and accessorie	es and/or subsequent restoration:		
Witness Corner to Meander Comer to	o Sections 5 and 32, T47/48	N-R30W on the East side of Gibson Lake.	RATIFIED BY PEER GROUP	
			P.A. 345 OF 1990	
W.C. M.C. C/D-13:			- Lagres & Bussine	
1846; W.A. John & Austin Burt D.S	marked a 10" Towards	for Meander Corner. No witnesses established.	DATE 11/4/96	
1984; R.L.S. No. 25836 found no	identifiable original evide	or Meander Corner. No wimesses established.		
Nails in: 7" Yellow Birch S60°E 11.	08'; 8" Yellow Birch S75*	W 5.16': 12" Twin Yellow Birch NASSW 13 221.	of Lakeshore by uncertain methodology witnessed by P.I 3" Balsam N25°E 11.25'. Recorded in L.4R.C., Pg. 422.	
			3" Balsam N25°E 11.25'. Recorded in L.4R.C., Pg. 422. eview of this certificae and others by the same firm show	
B. Description of corner evidence.	raight line from A-13 throu	gh B-13 to the meander corner G/H-13.	state of this continue and others by the same firm show	
a. a configuration of confict sylds	ence logito stichol Wet	hod applied in restoring or reestablishing co	orner:	
W.C. M.C. C/D-13:				
1996; ECI recovered capped rebar ab	out 30' East of Lakeshore.	No original corner evidence recovered. Review of	of survey certificate and field recovery of comers indicate	
West "over lake" ECT 15651 CL O	nced in part A was due to a	typographical error in L.C.R.C. preparation. The	of survey certificate and field recovery of comers indicate e following measurement was taken to G.L.O. terrain call	
careful and faithful re-establishment of	f the position of the arising	·13 is 2185.46' measured - G.L.O. 2269.74'. Com	e following measurement was taken to G.L.O. terrain call ner position established by acceptance of capped rebar as a	
	are beaution of the outling	comer. Distance East is 2185.46' and distance We	est is 1600.25'.	
			A STATE OF THE STA	
			Jul Alan X	
			# 27	
C. Description of monument fo	r corner and accessori	se actabliched to perpetuate to action u	# N mience \	
C. Description of monument fo	r corner and accessori	es established to perpetuate locating the po	osition of the corner.	
C. Description of monument fo	r corner and accessori	es established to perpetuate locating the po	osition of the corner:  LAND SURVEYOR	
1996:			osition of the corner.  PIERCE LAND SURVEYOR No. 30097	
1996: Replaced capped rebar with a 2-3/8" O.	D. siuminum pine carned	with a 2 state state of	osition of the corner.  PIER CE LAND SURVEYOR No. 30097	
1996: Replaced capped rebar with a 2-3/8" O. 0.8' above grade. Bearing trees are fa	.D. aluminum pipe capped	with a 3-1/4" aluminum tablet Marquette County S	osition of the corner:  LAND SURVEYOR No. 30097 No. 30097 AND Survey monument stamped to identify the corner set about	
1996: Replaced capped rebar with a 2-3/8" O. 0.8' above grade. Bearing trees are fa	.D. aluminum pipe capped	with a 3-1/4" aluminum tablet Marquette County S	osition of the corner:  LAND SURVEYOR No. 30097 No. 30097 AND Survey monument stamped to identify the corner set about	
Replaced capped rebar with a 2-3/8" O. 0.8' above grade. Bearing trees are fa distances measured from a duplex nail v	D. aluminum pipe capped ce, nail & butt blazed and with an orange washer stam	with a 3-1/4" aluminum tablet Marquette County S painted yellow with B.T. tags attached. Butt bla: ped "ECI-30097" in the side of the tree. Bearings a	osition of the corner:  LAND SURVEYOR No. 30097 No. 30097 AND Survey monument stamped to identify the corner set about	
Replaced capped rebar with a 2-3/8" O. 0.8' above grade. Bearing trees are fa distances measured from a duplex nail v. 8" Yellow Birch N75°E 14.03' (N.B.T.)	D. aluminum pipe capped ce, nail & butt blazed and with an orange washer stam	with a 3-1/4" aluminum tablet Marquette County S painted yellow with B.T. tags attached. Butt bla: ped "ECI-30097" in the side of the tree. Bearings a	osition of the corner:  LAND SURVEYOR No. 30097 No. 30097 AND Survey monument stamped to identify the corner set about	
Replaced capped rebar with a 2-3/8" O. 0.8' above grade. Bearing trees are fa distances measured from a duplex nail v	D. aluminum pipe capped ce, nail & butt blazed and with an orange washer stam	with a 3-1/4" aluminum tablet Marquette County S painted yellow with B.T. tags attached. Butt bla: ped "ECI-30097" in the side of the tree. Bearings a	Survey monument stamped to identify the comer set about ize is scribed "B.T.". Two 1984 trees were utilized with are magnetic.	
Replaced capped rebar with a 2-3/8" O. 0.8' above grade. Bearing trees are fa distances measured from a duplex nail v. 8" Yellow Birch N75°E 14.03' (N.B.T.)	D. aluminum pipe capped ce, nail & butt blazed and with an orange washer stam	with a 3-1/4" aluminum tablet Marquette County S painted yellow with B.T. tags attached. Butt bla: ped "ECI-30097" in the side of the tree. Bearings a "E 11.15"; 10" Yellow Birch S76*W 5.22';	Survey monument stamped to identify the comer set about ize is scribed "B.T.". Two 1984 trees were utilized with are magnetic.	