

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Marquette (County)	Located In:	Corner Code #
1. Public Land Survey	T 48N R 30W	E3
	T R	(GCDB 300600)
	T R	
2. Property Controlling in Section	S 4 T 48N R 30W	16
	S T R	(GCDB 360600)
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on E3 08/20/14
16 08/26/14 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(E3) Corner common to Sections 4-5-8-9. 1848 - Established by Wells Burt, Deputy Surveyor. Set
Y.Birch post. Sugar 10" S68°E 25 links, Sugar 20" N27°W 13 links. Found no subsequent record.

(16-Sec. 16) East 1/16 corner between Sections 4 & 9. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(E3) The original post and accessories were not recovered. Found no evidence of the position of the
original corner on the ground. Reestablished the position for the corner by double proportionate
measurement to the GLO record between monumented corners 2621.67' north (40.00 ch. R); 2614.13' east
(39.95 ch. R); 2619.69' west (40.05 ch. R); and 10486.27' south (160.00 ch. R).

(16) Corner not previously monumented. Established the position for the corner midway and on the
Section line between Section corner 1318.53' east and Quarter corner 1318.53' west. The position
for the corner falls in the W.Branch of the Peshekee River and cannot be monumented. Placed a
WITNESS CORNER on the Section line 71.38' west of the 1/16 corner position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(E3) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
11" Y.Birch S80°E 13.8' mrkd "S9 NBT"
3" Sugar S09°E 13.9' "S9 NBT"
6" Sugar S47°W 26.1' "S8 NBT"
6" Sugar N73°W 14.75' "S5 NBT"
Set sq'd Cedar post adjacent.
E= 7917579.233 N= 200060.616

(16) Set 1"IDx28" I.pipe with 2" alum. MDNR cap
71.38' west of the corner position and on the
Section line for a WITNESS CORNER.
Set measuring nail with MDNR tag in the side of:
6" Cherry N40°E 18.4' mrkd "WC BT"
6" Cherry S2°5E 19.2' do
3" Balsam West 6.65' do
13" Spruce N27°W 23.4' do
Set sq'd Spruce post adjacent.
E= 7918755.835 N= 200067.628 (the Witness cor.)

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum)
Coord. Ref.=NGS PID AA8080: N= 198400.952 m. E= 7925456.741 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 11/12/2014

For the Michigan Department of Natural Resources, Forest Resources Division

