## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

MARQUETTE COUNTY HEHIGAR PECCEVED FOR EUROPRO

1999 FEB 12 PM 3: 33

F	Preiden REGISTI	is d. Vi FIF OF DE	Amleys EDS Opt	
tegister	LIBER of Deed	R2	PACE 13 & File Nun	7

F

4 5

> 6 7

> > 9

10

11

DATE\_

MARQUETTE	in the	Located In	:	Corner Code #
(County)		Negaunee Town	nship	
I. Public Land Survey		T <u>48N</u>	R <u>26W</u>	A-02 V
		T <u>48N</u>	R <u>27W</u>	<u>M-02</u>
		T	R	<del></del>
		T	R	
2. Property Controlling	S	T	R	
in Section	s	T	R	
3. Miscellaneous	s	T	R	
Property in Sec.	S	T	R	

or corners in

\_ , Recorded Plat \_ 1. Lot No. Private Claims \_

, George M. Platz , in a field survey on <u>December 7</u>, 19 98 do nereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in ines 1 and 2 above were in conformance with regulations and rules therefore as required in the current nanual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1/4 corner common to: Section 6 T.48N., R.26W. Section 1 T.48N., R.27W.

RATIFIED BY PEER GROUP A. Description of original monument and accessories and/or subsequent restoration: P.A, 345 OF 1990

1844: Original U.S. Government Survey by Austin Burt - Set wood post witnessed by: S45°W 19 Links; 7" Maple

17 Links; 5" Maple N82°W

Section corner coordinate information from Cleveland Cliffs Iron Company indicates the corner to be a 1916 - 1918: 'standard" brass capped monument. No additional information given.

1982: Gerald Carlson PS 24589 found 1-1/4" iron pipe with brass cap (un-recorded) Source: Mead Paper notes. Witnessed

WBR 5 S83°E 10.91 by: RMP 4 S47°W 9.01' BSP 9 S84°W 14.21' CDR 3 N25°E 18.331

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1-1/2" iron pipe with "standard" brass cap, 24"+/- above ground, from remaining witnesses as delineated on 1982 Mead Paper notes. A thorough search found no evidence of any other survey monumentation or occupation in the immediate area. No evidence of original B.T.'s could be found. Original GLO line calls to natural features measure as follow:

South 1041' (R) 977' (M) Top of Rock South 1188' (R) 1176' (M) Top of Rock North 1254' (R) 1293' (M) River (Dry)

measurements, obtainable recorded survey information and any other obtained unrecorded survey information made available to Spalding DeDecker Associates is documented in the research dossier. Considering the above information, all known evidence favors the correctness of this point.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Accepted found 1-1/2" iron pipe with "standard" brass cap. Stamped "MCR 1998" on cap to properly identify the accepted corner. Made the following new witnesses:

18° 17.91'; Set mag nail w/tag No.38121 in W. face 4" Cedar.

4.21'; Set mag nail w/tag No.38121 in N. face of NW twin of 5" Maple. 9.89'; Set mag nail w/tag No.38121 in S. face 5" Maple. Az. 115°

Az. 282°

Az. 347° 21.31'; Set mag nail w/tag No.38121 in E. face 14" Pine with B.T. tag affixed.

GEORGE M.

FLATZ
SURJEYOR
SURJEYOR
SO
30121

George M. Platz

Date

Surveyor's Michigan License No. 38121