

SURVEY &  
REMONUMENTATION

JOB NUMBER: 94030  
SHEET NO. : 1-530

APR 28 1995

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

MARQUETTE COUNTY  
MICHIGAN  
RECEIVED FOR RECORD

1994 DEC 28 PM 5:58

For corners in

COMMISSION

MARQUETTE  
(County)

Located In:

Corner Code ##

- |                                       |                         |       |
|---------------------------------------|-------------------------|-------|
| 1. Public Land Survey                 | T 48N R 26W             | K13   |
|                                       | T _____ R _____         | _____ |
|                                       | T _____ R _____         | _____ |
|                                       | T _____ R _____         | _____ |
|                                       | T _____ R _____         | _____ |
| 2. Property Controlling<br>in Section | S _____ T _____ R _____ | _____ |
|                                       | S _____ T _____ R _____ | _____ |
| 3. Miscellaneous<br>Property in Sec.  | S _____ T _____ R _____ | _____ |
|                                       | S _____ T _____ R _____ | _____ |

*Patricia H. Monley*  
REGISTER OF DEEDS

LIBER 1 PAGE 196  
Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, GERALD W. CARLSON, in a field survey on Thursday, November 24, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

K-13: Section Corner common to Sections 35 and 36, T48N-R26W. 1992: A Land Corner Recordation Certificate filed by 1844: William A. Burt's original survey notes described the corner monument as a wood post, referenced by:

10" Cedar, N84E, 25 l	G. Carlson restored corner position from coordinate position noted in information from CCI files. Set 5/8" re-rod w/LLS cap no. 24589 referenced by:
20" Cedar, N45W, 9 l	7" Poplar, N09W, 10.68'
	4" Poplar, N49W, 13.25'
	10" Poplar, S65W, 17.49'
	8" Poplar, S22E, 23.29'

Liber SRC, Page 372.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1994: Found and accepted the iron w/LLS cap as referenced above in Part A.  
Distance West is 5268.86' and distance East is 2632.85'. Section Corner common to Sections 1 and 2, T47N-R26W is West 38.28'.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1994 - Replaced 5/8" iron and cap #24589 with a 2 1/2" diameter aluminum pipe capped with a 3 1/4" diameter aluminum tablet Marquette County Survey Monument stamped to identify the corner referenced by nails in:

6" Poplar N06W 10.66 ft. Carlson NBT
8" Poplar S24E 23.39 ft. Carlson NBT
10" Poplar S67W 17.53 ft. Carlson NBT
4" Poplar N43W 13.23 ft. Carlson NBT

Steel sign post North 1.0 ft.  
Monument is 0.5' above ground and is +/- 99' South of old railroad grade.  
Bk. 7, Pg. 137

RATIFIED BY PEER GROUP  
P.A. 345 OF 1990

*Larry J. Bussard*  
DATE Nov 7, 1994

Signed by Gerald W. Carlson Date 12-22-94  
Surveyor's Michigan License No. 24589

