APR 1 1 1996

COMMISSICAND CORNER RECORDATION CERTIFICATE JOB NUMBER: 95053 SHEET NO. : 1-657 Filing Requirement of Act 74, Mich. P.A. 1970 For corners in Located In: Corner Code # MARQUETTE (County) T48N _ R^{27W} 1. Public Land Survey T48N R^{26W} Т 2. Property Controlling S ____ R _ in Section __т__ LIBER 3. Miscellaneous Register of Deeds Stamp & File Number Property in Section _ , Recorded Plat _ 4. Lot No. 5. Private Claims Wednesday, December _ , in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found NOTE: Not more than 4 corners, all in the same town and range, may be recorded A. Description of original monument and accessories and/or subsequent restoration: M-11/12: Meander Corner North of the Quarter Corner common to Section 36, T48N-R27W and Section 31, T48N-R26W. 1844: Austin Burt's original survey notes describe the corner monument as a wood post referenced by: 10" Tamarack N03W. 21 1 B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: 1995: Original Meander Corner falls in Teal Lake. Set a Witness Corner grouted in rock 150.00' North of the prorated calculated Meander Corner on line between the N.B. and S.E. Corners of Section 36. Distance North is 1787.43' and Distance South is 3457.70'. RATIFIED BY PEER GROUP C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: 1995: Set a 3/4" X 12" rebar, grouted in rock, and capped with a 3 1/4" aluminum tablet Marquette County Survey Monument, 0.15' above ground, and stamped to identify the corner. Established references using duplex nails set in: 15" W. Pine N46B, 66.45' TE OF HICH 7" W. Pine NIIW, W. Pine N81W. 31.11' GERALD W S62W, 58.531 CARLSON Green Steel Fence Post w/Survey Monument Sign N85E, 2.16' SURVEYOR Note: Bearing trees were face and butt blazed, painted, and had B.T. Tags affixed. Bk. 10, PP. 57-58. No. 24589 Guald W Carlson FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 Surveyor's Michigan License No._

REVISED MAY 14, 1975