

SURVEY &  
REMONUMENTATION

FEB 21 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MARQUETTE

(County)

Located In:

Corner Code #

1. Public Land Survey

T 48N R 26W

J-1

T      R     

T      R     

T      R     

T      R     

2. Property Controlling  
in Section

S     

T      R     

S     

T      R     

3. Miscellaneous  
Property in Sec.

S     

T      R     

S     

T      R     

4. Lot No.         , Recorded Plat         

5. Private Claims                                 

I, GERALD W. CARLSON, in a field survey on December 1 ST, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE:** Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

**A. Description of original monument and accessories and/or subsequent restoration:**

J-1: North Quarter Corner of Section 2, T48N-R26W.

Corner not established during Original GLO Survey.

No subsequent record evidence recovered.

**RATIFIED BY PEER GROUP  
P.A. 345 OF 1990**

DATE 11/6/00

**B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:**

J-1: 2000: SCA survey crews conducted a thorough search of the area and found no evidence of monumentation except an East-West brush line with paint and flagging. Corner position was established equidistant between the NW and NE corners of Section 2 and on line between the SE and S 1/4 corners of Section 35, T49N-R26W. Monument falls on the East-West brush line.

**C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:**

J-1: 2000: Set a 2 3/8" O.D. aluminum pipe capped with a 3 1/4" diameter aluminum tablet Marquette County Survey Monument stamped to identify the corner. Monument is 0.75' above ground as the monumentation crew hit bed rock at about 2'. Referenced by:

9" Maple N10E, 6.56' 7" Maple N55E, 13.65'

14" Hemlock S45W, 23.10' 7" Hemlock N87W, 33.21'

South 1/4 Corner Section 35, T49N-R26W S89°51'51"W, 15.84'

Green Steel Sign Post w/ Yellow Survey Marker Sign S13W, 3.00'

Distance East 2640.35', distance West 2640.35'.

Note: Bearing trees have painted face, butt, and side nail blazes, d.h. measuring nails, and stamped B.T. Tags affixed.

Bk. 15, Pg. 87 T48N-R26W Corner Search Sheet 2000035

Signed by

Gerald W Carlson

Date

12-19-00

Surveyor's Michigan License No.

24589

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS

REVISED MAY 14, 1975  
REVISED JAN., 1983  
REVISED OCT., 1995

MARQUETTE COUNTY  
MICHIGAN  
RECEIVED FOR RECORD

2000 DEC 22 AM 10:18

*Patricia A. Mosley*  
REGISTER OF DEEDS

**LIBER R2 PAGE 291**

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

