

1993

COMMISSION

JOB NUMBER: 93300

SHEET NO. : 1-411

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MARQUETTE

(County)

Located In:

Corner Code ##

1. Public Land Survey

T 47N R 27W

MC C/D-1

T 48N R 27W

MC C/D-13

T R

T R

2. Property Controlling in Section

S T R

S T R

3. Miscellaneous

S T R

Property in Sec.

S T R

4. Lot No. , Recorded Plat

5. Private Claims

I, GERALD W. CARLSON, in a field survey on Wednesday, December 29, 1993

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

MC C/D-1: Meander Corner West of Quarter Corner common to Section 5, T47N-R27W and Section 32, T48N-R27W. 1846: Austin Burt's original survey notes describe the corner monument as a wood post referenced by:  
7" Cedar S10W, 31 l  
12" Tamarack N23W, 28 l  
(West side Cooper Lake)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1993 - Meander corner was calculated proportional distance and on line between the NE and the NW corner of Section 5, T47N-R27W.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1993 - Set a 2 1/8" diameter aluminum pipe capped with a 3 1/4" diameter aluminum tablet Marquette County Survey Monument stamped to identify the corner referenced by nails in:  
15" Cedar N17E 12.96 ft.  
9" Cedar N72E 10.98 ft.  
6" Cedar S39E 17.38 ft.  
9" Maple N80W 26.58 ft.  
Monument is 0.40 ft. above grade, 19.5 ft. West of water's edge of Cooper Lake.  
No blazes or BT tags set due to residential nature of corner position.  
Bk. 5, Pg. 36

LIBER

1 PAGE

95

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													



Signed by Gerald W. Carlson

Date 12-29-93

Surveyor's Michigan License No. 24589