

JOB NUMBER: 95053
SHEET NO. : 1-657

APR 6 1996

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MARQUETTE
(County)

Located In:

Corner Code #

1. Public Land Survey

T48N R27W

M-11/12 (3)

T48N R26W

A-11/12 (1)

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous

S T R

Property in Section

S T R

4. Lot No. , Recorded Plat

5. Private Claims

I, GERALD W. CARLSON, in a field survey on Wednesday, December 6, 1995

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

M-11/12: Meander Corner North of the Quarter Corner common to Section 36, T48N-R27W and Section 31, T48N-R26W. 1844: Austin Burt's original survey notes describe the corner monument as a wood post referenced by:
10" Tamarack N03W, 21 l

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1995: Original Meander Corner falls in Teal Lake. Set a Witness Corner grouted in rock 150.00' North of the prorated calculated Meander Corner on line between the N.E. and S.E. Corners of Section 36. Distance North is 1787.43' and Distance South is 3457.70'.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1995: Set a 3/4" X 12" rebar, grouted in rock, and capped with a 3 1/4" aluminum tablet Marquette County Survey Monument, 0.15' above ground, and stamped to identify the corner. Established references using duplex nails set in:

| | | |
|---|-------|--------|
| 15" W. Pine | N46E, | 66.45' |
| 7" W. Pine | N11W, | 26.41' |
| 7" W. Pine | N81W, | 31.11' |
| 16" W. Pine | S62W, | 58.53' |
| Green Steel Fence Post w/Survey Monument Sign | N85E, | 2.16' |

Note: Bearing trees were face and butt blazed, painted, and had B.T. Tags affixed.

Bk. 10, PP. 57-58.

RATIFIED BY PEER GROUP
P.A. 345 OF 1990

DATE

12/04/95

Signed by

Gerald W. Carlson

Date

12-20-95

Surveyor's Michigan License No.

24589

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983

MARQUETTE COUNTY
MICHIGAN
RECEIVED FOR RECORD
1995 DEC 27 AM 7:50
REGISTER OF DEEDS

LIBER 1 PAGE 302
Register of Deeds Stamp & File Number

| | A | B | C | D | E | F | G | H | I | J | K | L | M |
|----|----|---|----|---|----|---|----|---|----|---|----|---|---|
| 2 | 6 | | 5 | | 4 | | 3 | | 2 | | 1 | | |
| 3 | | | | | | | | | | | | | |
| 4 | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | | |
| 5 | | | | | | | | | | | | | |
| 6 | 18 | | 17 | | 16 | | 15 | | 14 | | 13 | | |
| 7 | | | | | | | | | | | | | |
| 8 | 19 | | 20 | | 21 | | 22 | | 23 | | 24 | | |
| 9 | | | | | | | | | | | | | |
| 10 | 30 | | 29 | | 28 | | 27 | | 26 | | 25 | | |
| 11 | | | | | | | | | | | | | |
| 12 | 31 | | 32 | | 33 | | 34 | | 35 | | 36 | | |
| 13 | | | | | | | | | | | | | |

