SURVEY & REMONUMENTATION

FEB

Ü

3 2 1 2001		MARQUETTE COUNTY MICHIGAN RECEIVED FOR RECORT	
	I AND CODNED DECODDATION CERTIFICATE	om DEC 22 AM IO: 17	

SECTION		ment of Act 74, Mich. P.A. 1		
For corners in	r ming recognition	Interior Floring in Interior is a second	Patricia d. Monlay REGISTER OF BEEDS OF	
MARQUETTE	Located In:	Corner Code #	Tables a. Thomsey	
(County)			REGISTER OF DEEDS OF	
1. Public Land Survey	T_49N R_26W _	C-13	•	
	TR			
	т <u></u> Ř <u>.</u>			
	TR			
2. Property Controlling	S TR			
in Section	S T R		A A'	-
3. Miscellaneous	S T R		LIBER ${f R}$ ${f Z}$ PAGE ${f Z}'$	13
Property in Sec.	S T R			
		L	Register of Deeds Stamp & File Nu	ımbe
4. Lot No, Reco	rded Plat			
5. Private Claims			- ABCDEFGHIJK	K L
			2 - 6 - 5 - 4 - 3 - 2	1-1-
		tober 19 th , 2000 , do hereby		$\vdash \vdash$
state that under requirements of lines 1 and 2 above were in con	· · · · · · ·		4 6 6 7 17	12
current manual of survey instruc	• · · · · · · · · · · · · · · · · · · ·			
Land Management or by a decree				
3, 4 and 5 above were in conformation			8 - 18 - 17 - 13 - 13 - 14 - 1	13
by a Decree of a Court of Law		-		\vdash
expressed below:			8 19 20 21 22 23	2,4-
			9	 -
	ners, all in the same town and	I range, may be recorded	10 30 29 28 27 26	25
on this certificate.				LĪ.
				\prod
A. Description of original mor		or subsequent restoration:	12 31 32 33 34 35	36
C-13: Corner common to Sect 1844: Austin Burt's original To	ions 31 & 32, 149N-R20VV.	T40N.P26W/ describe the	13RATIFED BY PEER GROUP	LL.
corner monument as a wood p		14914-1120W, describe the	P.A. 345 OF 1990	
14" Hemlock N56E,	25 links 10" Maj	ple N52W, 34 links	Larry Busson	
7107110011	20 11110	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	DATE 11/6/00	
1981: Robert E. Schmeling for	und a ½" dia. By 4' long iron	pin and accepted it as the	/ /	
Section Corner Common to Se	ections 5 & 6, T48N-R26W ar	nd Sections 31 & 32, T49N-R2	26W. Mr. Schmeling verified this location	by
Original BT evidence he recove	ered, which witnessed the Co	rner Common to Sections 31	& 32. Mr. Schmeling placed a 1" dia. By	4'
			lished the following references:	
Hard Maple 7"		32 T49N R26W NBT)		
Hard Maple 7"	•	T48N R26W NBT)		
Hemlock 7" Hard Maple 8"	•	5 T48N R26W NBT) 31 T49N R26W NBT)		
5" Cedar Post/Tag	North, 2'	7 143N N20W ND1)		
0 00dd; 10dd; 1dg				
B. Description of corner evidence	ence found and/or method ap	plied in restoring or reestablish	ling corner:	
C-13: 2000: Found and accept	oted as the Southeast Corner	of Section 31, T49N-R26W th	ne Robert Schmeling monument described	in :
part A above. Mr. Schmeling	incorrectly stamped this mor	nument as the Corner common	to Sections 5 and 6, T48N-R26W and sec	CTIONS
31 and 32, T49N-R26W. Du	ring the monumentation of th	le Northeast Corner of Section	6, T48N-R26W we dug away the topsoil	anu
subsequent wood post if not t			ting. It is very likely that this is an old	
subsequent wood post in not t	ne onginal GEO post commin	ing the closing comer recation		
C. Description of monument	for corner and accessories es	stablished to perpetuate locatin	g the position of the corner:	
C-13: 2000: We accepted th	e found monument identified	in part A above and since it w	as in good condition and stable, did not re	eplace
it. Monument is now stamped	∄ "MCR 2000" and is 1.3' ab	ove ground on the Southweste	erly side of County Road 510 approximatel	ly 75
from centerline and 20' above			S C60F 11 92	
	N75E, 14.94'	6" Maple (RES NBT		
9" Hemlock (RES NBT)		7" Maple (RES NBT) N85W, 24.26'	
Northeast Corner of Section 6		VV, 10.70	Court In	
4" Square Cedar Post w/ tag Distance East 2638.37', dista			State on anchie	
Note: Bearing trees have paint		lazes, d.h. measuring nails.		
and stamped B.T. Tags affixed			GERALD W.	à
Bk. 15, Pg. 45 T49N-R26W		35	CARLSON +	N
	÷		SURVEYOR *	G)



Signed by June 1	wiso-	DateDate
Surveyor's Michigan License No	24589	FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14,1975 REVISED JAN., 1983 REVISED JOCT., 1995