SURVEY & REMONUMENTATION

FEB 21 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

MARQUETTE COUNTY MICHIGAN RECEIVED FOR RECORD

200 DEC 12 PM 2: 29

Patricia REGISTER	A.	Mone	laces
REGISTER	OF	DÈEDS	Shu.

51N R 29W R	A-11
R	
Γ R Γ R	
ΓR ΓR	
t	
	RR

 ${f R}$ 2, page 244IRFR Register of Deeds Stamp & File Number

in a field survey on April 16 state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed

NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration: A-11: Southwest Corner of Section 30: 1845: Austin Burt's original township line survey notes describe the corner as a post referenced by: 14" Lynn S45W, 17 L N68W 13 L

1846: William Ives's original subdivision notes for T51N-R29W added the following two references: 24" Y. Birch N86E, 26 L S78E, 29 L 6" Fir

2 3 6

> RATIFIED BY PEER GROUP P.A., 345 OF 1990 Busome 100 DATE

1974: A land corner recordation certificate by Robert E. Schmeling, RLS No. 8317 and recorded in Liber 1, Page 153 indicates he found a 5" Hemlock post and 1" iron pipe set by Norm Thompson RLS No. 4348 from the 24" Y. Birch BT. Schmeling set a 1" dia. By 4' long galvanized iron pipe stamped to identify the corner referenced by: 8.5" Sugar Maple S47E, 22.7' to c/l tree, 5.2" Sugar Maple S55W, 32.0 to c/l tree, 7.8" Sugar Maple, N83E, 31.7' to c/l tree.Thompson's NBT's a 6" Ironwood S33W, 18.7'(Gone) and a 6" Sugar Maple N50W, 27.3'to notch (now 12" with lower blaze cut out showing scribe marks).

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A-11: 2000: Found a 1" dia. By 4' long galvanized iron pipe with Mead Corp. brass cap stamped to identify the corner leaning at a 45 degree angle. Also found Schmeling's NBT's S55W and N83E. The S47E NBT was apparently cut by loggers. The area was mostly clear cut several years ago. Blue paint lines N-S and E-W from corner. Corner falls in rocky clay soil. Dug down 30" and replaced the corner from the two remaining Schmeling NBT's. Check measurement to the c/l of the S47E Schmeling NBT stump is 22.76' (Record 22.7'). The corner projects 15" above ground and also placed an 8" spike deadman in the existing hole near the bottom of the 1" dia. Pipe. The corner falls at the North end of an old clear cut area 28' +- North of the c/l of a skid trail accessible by 4 wheeler ATV.

Description of monument for corner and accessories established to perpetuate locating the position of the corner: C.

A-11: 2000: A 1" by 4' long gal. iron pipe with Mead Corp. brass cap stamped to identify the corner referenced by 20d duplex nails in:

13" Maple N86E, 31.70' (Schmeling NBT)

9" Maple S60W, 32.00' (Schmeling NBT)

7" Maple N85W, 24.65'

6" Maple N21W, 27.57'

6' green steel fence post with sign, North, 4.6'

Note: Bearing trees have painted face, butt and side nail blazes and engraved BT tags affixed.

Gudd Warlson Surveyor's Michigan License No. 24589

Date 8-21-00

TE OF MICHIG GERALD W CARLSON CI IDVEYOR No. 24589 ROFESSION