

FEB 11 1998

SECTION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

Approved by Performance Unit  
Land Survey Remonumentation  
Peer Group Under Act 345 Of  
P.A. Of 1990 On 10/31 199 7  
McDermott DLS  
Chairman

For corners in  
MENOMINEE

(County)

Located In:

Corner Code #

1. Public Land Survey

T~~32~~N R~~28~~W

M-2

T~~32~~R~~27~~

A-2

2. Property Controlling  
in Section

S~~32~~T~~28~~R~~27~~

3. Miscellaneous  
Property in Sec.

S~~32~~T~~28~~R~~27~~

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

SAME AS CORNER A-2, T32N-R27W

I, William Lenca, in a field survey on Mar. 26, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1847: Original Survey by John Mullett - B.T.'s - B. Ash, 18" - N68°W - 35 lks.; Cedar, 10" - S20°W - 30 lks. No original evidence for this corner was recovered.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

This corner was re-established at a single proportional location between the NE Corner (M-1) and the SE Corner (M-3) of Section 1, and is accepted as a careful and faithful reestablishment of the position of the original corner. This corner falls in a large tag alder swamp - there is no evidence of occupation in the area.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 2" dia. Aluminum Pipe/3-1/4" dia. Alum cap stamped for corner location:

5" dia. Maple	S59°E	54.75 feet	Scr. NBT
7" dia. White Ash	S35°E	23.26 feet	Scr. NBT
6" dia. Maple	S86°W	8.08 feet	Scr. NBT
8" dia. White Birch	N20°W	46.27 feet	Scr. NBT
Metal Survey Sign Post	South	0.2 feet	

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Lenca  
Surveyor's Michigan License No. 26461

Date Apr. 08, 1997

