

# SURVEY & REMONUMENTATION

JAN 09 2001

## SECTION

### LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Approved by Menominee County  
Land Survey Remonumentation  
Peer Group Under Act 345 of  
P.A. Of 1990 On Dec. 2000  
Mr. David RLS  
Chairman

For corners in

MENOMINEE

(County)

Located In:

Corner Code #

1. Public Land Survey

T33N R 26W

C-8

2. Property Controlling  
in Section

S  
S

T  
T

3. Miscellaneous  
Property in Sec.

S  
S

T  
T

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

I, William Lenca, in a field survey on Dec., 1900 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A	B	C	D	E	F	G	H	I	J	K	L	I
1												
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

A. Description of original monument and accessories and/or subsequent restoration:

- 1848: Original Survey by James H. Mullett - B.T.'s - Tamarack, 6" - N07°W - 10 lks.; Tamarack, 6" - S07°E - 8 lks. All original evidence for this corner has been destroyed by Logging activities.
- 1988: L.C.R.C. No. 803 by William Lenca, RLS No. 26461 - Found very old Sqd Ced. Post & blazes leading N - S & E. Fits existing occupation to the West. Set 3/4" x 60" Alum. Pipe/3" cap - TIES: B. Spruce, 5" - S02°W - 29.71'; Hemlock, 8" - S70°E - 50.96'; Balsam, 6" - N22°E - 6.87'; Carsonite - N72°W - 1.58'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

We recovered a 3/4" x 60" aluminum pipe with a 3-1/4" aluminum cap and 3 B.T.'s as described in L.C.R.C. No. 803 (see part "A"). We also found the remains of the old squared wood post mentioned above. There is an East - West County Road running from the W1/4 Corner East for 3/4 of a mile. The centerline of this road extended East fits this old post. The measurement East from the C1/4 corner to an old 1/16 fence is 1354 feet and the measurement from this fence East to the old post is 1365 feet. This matches the old 1/16 fence within 5.5 feet. This corner fits reasonably well with measurements to other corners in the area, has been used for control for surveys in Section 20, T33N-R26W, and is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Accepted existing 3/4" x 5' long aluminum rod/3-1/4" dia. Alum. cap stamped for corner:

8" dia. Maple	N25°E	13.62 feet	Scr. NBT
12" dia. Hemlock	S38°E	43.44 feet	Scr. NBT
6" dia. Black Spruce	S10°E	49.06 feet	Scr. NBT
8" dia. Maple	N75°W	10.62 feet	Scr. NBT
Carsonite Marker	North	0.8 feet	

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Lenca  
Surveyor's Michigan License No. 26461

Date Dec. 20, 2000

